

**STATE OF NEVADA
DIVISION OF WATER RESOURCES
WELL DRILLER'S PLUGGING REPORT**

OFFICE USE ONLY
Log No. 1198504
Permit No. _____
Basin 105

**PRINT OR TYPE ONLY
DO NOT WRITE ON BACK**

*Please complete this form in its entirety in
accordance with NRS 534.170 and NAC 534.340*

NOTICE OF INTENT NO. 69881

1 OWNER A&A Construction ADDRESS AT WELL LOCATION Near intersection of Lasso Lane and Heybourne Road in Gardnerville, NV.
MAILING ADDRESS P.O. Box 995 Minden, NV. 89423 Subdivision Name: The Ranch @ Gardnerville County: Douglas

2 LOCATION SW 1/4 NW 1/4 Sec 33 T 13N N/S R 20 E Latitude 38 56.883 N UTM E NAD 27
PERMIT/WAIVER No. _____ Longitude 119 44.978 W N NAD 83/WGS 84
Issued by Water Resources Parcel No.

3 TYPE OF WELL
 Domestic Irrigation Test
 Municipal/Industrial Monitor Stock
Is this well being plugged because a replacement well was drilled? no
Is there an existing well log? yes
If yes, what is replacement well NOI? _____ If yes, what is NDWR well log #? 106269

4 EXISTING WELL CONSTRUCTION
Depth Drilled 20 Feet Depth Cased 18.9 Feet

| EXISTING CASING SCHEDULE | | | | |
|--------------------------|---------------------|-------------------------|-------------|-----------------|
| Size O.D. (Inches) | Weight/Ft. (Pounds) | Wall Thickness (Inches) | From (Feet) | To (Feet) |
| 10 | 8.68 | .413 | 0 | 18.9 |
| | | | | <u>20</u> |

Existing Perforations:
Type of perforation hand slotted
Size of perforation 1/4"
From 10 feet to 20 feet
From _____ feet to _____ feet

5 WATER LEVEL
Static water level 6.5 feet below land surface
Artesian flow _____ G.P.M. _____ P.S.I.
Water temperature _____ °F Quality _____

6 Additional Notes or Comments
No pump in well. Installed tremme, pumped in neat cement and pulled casing from well.

*#DW-17 NAD27
38.948500N
119.749633W*

*2013 NOV 15 PM 2:00
STATE ENGINEERS OFFICE
plugs well log 106269*

7 WELL PLUGGING PROCEDURE
Was well cleaned out to total depth? yes no
If well was not cleaned out to total depth, please explain why: _____

Was the well contaminated? yes no
Was the casing pulled? yes no
Was the casing over drilled? yes no
If casing was left in place, please show where additional perforations were made:
Additional Perforations:
Type of perforator used:
From _____ feet to _____ feet Number of perfs per linear foot _____
From _____ feet to _____ feet Number of perfs per linear foot _____
From _____ feet to _____ feet Number of perfs per linear foot _____
From _____ feet to _____ feet Number of perfs per linear foot _____
From _____ feet to _____ feet Number of perfs per linear foot _____
From _____ feet to _____ feet Number of perfs per linear foot _____

8 WELL PLUGGING MATERIALS
From 0 feet to 18.9 feet neat cement Pumped Poured
From _____ feet to _____ feet Pumped Poured

Neat Cement Fluid Weight 14.5 lbs/gal
Bentonite Grout _____ % bentonite
Date Started 10/7/2013
Date Completed 10/9/2013

9 DRILLER'S CERTIFICATION
This well was plugged and abandoned under my supervision and the report is true to the best of my knowledge.
Name Carson Pump, LLC Contractor
Address P.O. Box 20159 Contractor
Carson City, NV. 89721
Nevada contractor's license number issued by the State Contractor's Board 39920A
Nevada driller's license number issued by the Division of Water Resources, the on-site driller 2265
Signed [Signature] By driller performing actual drilling on site or contractor
Date 10/22/2013