

STATE OF NEVADA  
DIVISION OF WATER RESOURCES  
**WELL DRILLER'S PLUGGING REPORT**

OFFICE USE ONLY  
Log No. 1150  
Permit No. 76979  
Basin 139

PRINT OR TYPE ONLY  
DO NOT WRITE ON BACK

Please complete this form in its entirety in accordance with NRS 534.170 and NAC 534.340

NOTICE OF INTENT NO. 70630

1. OWNER Quadra Robinson NV Mining **RW-5P** ADDRESS AT WELL LOCATION Robinson Mine, 2 Miles South of Ruth, NV.  
MAILING ADDRESS P.O. Box 382  
Ruth, NV. 89319 **Subdivision Name:** \_\_\_\_\_ **County:** White Pine

2. LOCATION SW¼NE¼ Sec14T16N/ R62E Latitude \_\_\_\_\_ UTM E 675975  NAD 27  
PERMIT/WAIVER NO. 76979 Longitude \_\_\_\_\_ N 4346532  NAD 83/WGS 84  
*Issued by Water Resources* Parcel No. \_\_\_\_\_

3. TYPE OF WELL \_\_\_\_\_ Is this well being plugged because a replacement well was drilled?  Yes  No  
 Domestic  Irrigation  Test  Monitor  Stock  
 Municipal/Industrial  Monitor  Stock  
If yes, what is replacement well NOI? \_\_\_\_\_ Is there an existing well log?  Yes  No  
If yes, what is NDWR well log #? 106186

4. **EXISTING WELL CONSTRUCTION**  
Depth Drilled 1220 Feet Depth Cased 1197 Feet

**EXISTING CASING SCHEDULE**

| Size O.D. (Inches) | Weight/Ft. (Pounds) | Wall Thickness (Inches) | From (Feet) | To (Feet) |
|--------------------|---------------------|-------------------------|-------------|-----------|
| 32.0               | 168.21              | .500                    | 0           | 96        |
| 20.00              | 78.60               | .375                    | +2          | 1197      |
| 2.375              | 5.02                | .218                    | +2          | 1197      |

**Existing Perforations:**  
Type of perforation Full Flo Louvered  
Size of perforation .125

|  |
|--|
| From <u>556</u> feet to <u>1197</u> feet |
| From _____ feet to _____ feet            |
| From _____ feet to _____ feet            |
| From _____ feet to _____ feet            |
| From _____ feet to _____ feet            |

5. **WATER LEVEL**  
Static water level: 725 feet below land surface  
Artesian flow: N/A G.P.M. N/A P.S.I.  
Water Temperature: \_\_\_\_\_ °F Quality \_\_\_\_\_

6. Additional Notes or Comments  
**Waiver # W-629**  
**Waiver # R3D-13-12**

**Hole Plug was poured while pumping abantonite after the plugging requirement was met.**

**Material used in 20" casing**  
**160 Cu/Ft. Neat Cement.**  
**2325.6 Cu/Ft. Abantonite**  
**168.7 Cu/Ft. Hole Plug**  
**526.5 Cu/Ft. Clean Native Fill**

**Material used in 2" sounder pipe**  
**26 Cu/Ft. Abantonite**  
**5.9 Cu/Ft. Neat Cement**

7. **WELL PLUGGING PROCEDURE**  
Was well cleaned out to total depth?  Yes  No  
If well was not cleaned out to total depth, please explain why: \_\_\_\_\_

Was the well contaminated?  Yes  No  
Was the casing pulled?  Yes  No  
Was the casing over drilled?  Yes  No  
If casing was left in place, please show where additional perforations were made:  
**Additional Perforations:**  
Type of perforator used: Holte

|   |   |
|---|---|
| From <u>426</u> feet to <u>556</u> feet | Number of perfs per linear foot <u>24</u> |
| From _____ feet to _____ feet           | Number of perfs per linear foot _____     |
| From _____ feet to _____ feet           | Number of perfs per linear foot _____     |
| From _____ feet to _____ feet           | Number of perfs per linear foot _____     |
| From _____ feet to _____ feet           | Number of perfs per linear foot _____     |
| From _____ feet to _____ feet           | Number of perfs per linear foot _____     |

8. **WELL PLUGGING MATERIALS**  
**Material Used**

|  |                  |  |
|--|------------------|--|
| From <u>0</u> feet to <u>20</u> feet     | <u>Neat C.</u>   | <input type="checkbox"/> Pumped <input checked="" type="checkbox"/> Poured |
| From <u>20</u> feet to <u>410</u> feet   | <u>Native M.</u> | <input type="checkbox"/> Pumped <input checked="" type="checkbox"/> Poured |
| From <u>410</u> feet to <u>433</u> feet  | <u>Neat C.</u>   | <input checked="" type="checkbox"/> Pumped <input type="checkbox"/> Poured |
| From <u>433</u> feet to <u>1197</u> feet | <u>Abant.</u>    | <input checked="" type="checkbox"/> Pumped <input type="checkbox"/> Poured |
| From _____ feet to _____ feet            | _____            | <input type="checkbox"/> Pumped <input type="checkbox"/> Poured            |
| From _____ feet to _____ feet            | _____            | <input type="checkbox"/> Pumped <input type="checkbox"/> Poured            |

Neat Cement Fluid Weight 15.6 lbs/gal  
Bentonite Grout 20 % bentonite  
Date Started November 1, 2013  
Date Completed November 4, 2013

9. **DRILLER'S CERTIFICATION**  
This well was plugged and abandoned under my supervision and the report is true to the best of my knowledge.

Name Boart Longyear (CONTRACTOR)  
Address 2745 California Ave. (CONTRACTOR)  
SLC., UT. 84104  
Nevada contractor's license number issued by the State Contractor's Board 0021976  
Nevada driller's license number issued by the Division of Water Resources, the on-site driller 2308  
Signed \_\_\_\_\_  
By driller performing actual drilling on site or contractor  
Date November 7, 2013

RECEIVED  
2013 NOV 12 AM 11:38  
STATE ENGINEERS OFFICE

*Plugs well log 106186*  
*NAD27*  
*39.252149°N*  
*114.960643°W*