

STATE OF NEVADA
DIVISION OF WATER RESOURCES
WELL DRILLER'S PLUGGING REPORT

OFFICE USE ONLY
Log No. 118817
Permit No. _____
Basin 212

PRINT OR TYPE ONLY
DO NOT WRITE ON BACK

Please complete this form in its entirety in
accordance with NRS 534.170 and NAC 534.340

NOTICE OF INTENT NO. 37111

1 OWNER Furniture Plaza MLK LLC ADDRESS AT WELL LOCATION 73 S. Martin Luther King Blvd
MAILING ADDRESS 1 Ashley way. A Las Vegas, Nv 89106
Arcadia W. 54612-1218 Subdivision Name: _____ County: Clark

2 LOCATION SW 1/4 SE 1/4 Sec 28 T 20S N/S/R 61 E Latitude 36.173600 UTM E _____ NAD 27
PERMIT/WAIVER No. 139-33-510-002 Longitude -115.159036 N _____ NAD 83/WGS 84
Issued by Water Resources Parcel No. _____

3 TYPE OF WELL Domestic Irrigation Test Municipal/Industrial Monitor Stock
Is this well being plugged because a replacement well was drilled? no
If yes, what is replacement well NOI? _____
Is there an existing well log? yes
If yes, what is NDWR well log #? 113737

4 EXISTING WELL CONSTRUCTION
Depth Drilled 26 Feet Depth Cased 25 Feet

EXISTING CASING SCHEDULE

Size O.D. (Inches)	Weight/Ft. (Pounds)	Wall Thickness (Inches)	From (Feet)	To (Feet)
<u>2"</u>		<u>sch 40</u>	<u>0</u>	<u>25</u>

Existing Perforations:

Type of perforation	Size of perforation	From	feet to	feet
<u>factory slotted</u>	<u>0.02</u>	<u>10</u>	<u>25</u>	<u>feet</u>

7 WELL PLUGGING PROCEDURE
Was well cleaned out to total depth? yes no
If well was not cleaned out to total depth, please explain why: _____

Was the well contaminated? yes no
Was the casing pulled? yes no
Was the casing over drilled? yes no
If casing was left in place, please show where additional perforations were made:
Additional Perforations:
Type of perforater used: _____

From	feet to	feet	Number of perfs per linear foot

5 WATER LEVEL
Static water level _____ feet below land surface
Artesian flow _____ G.P.M. _____ P.S.I.
Water temperature _____ °F Quality _____

8 WELL PLUGGING MATERIALS

Material Used

From	feet to	feet	Material	<input checked="" type="checkbox"/> Pumped	<input type="checkbox"/> Poured
<u>25</u>	<u>0</u>	<u>feet</u>	<u>quik grout</u>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
				<input type="checkbox"/>	<input type="checkbox"/>
				<input type="checkbox"/>	<input type="checkbox"/>
				<input type="checkbox"/>	<input type="checkbox"/>
				<input type="checkbox"/>	<input type="checkbox"/>
				<input type="checkbox"/>	<input type="checkbox"/>

6 Additional Notes or Comments

DCNR/DWR/SNB
RECEIVED
DEC 04 2013
mw-9

Neat Cement Fluid Weight _____ lbs/gal
Bentonite Grout _____ % bentonite
Date Started 10/28/2013
Date Completed 10/28/2013

9 DRILLER'S CERTIFICATION

This well was plugged and abandoned under my supervision and the report is true to the best of my knowledge.
Name Eagle Drilling LLC. Contractor
Address 7150 Placid St., Las Vegas, Nv., 89119 Contractor
Nevada contractor's license number issued by the State Contractor's Board 51266
Nevada driller's license number issued by the Division of Water Resources, the onsite driller 2490-LTD
Signed [Signature] By driller performing actual drilling on site or contractor
Date 11/14/2013