

**STATE OF NEVADA  
DIVISION OF WATER RESOURCES  
WELL DRILLER'S PLUGGING REPORT**

**OFFICE USE ONLY**  
Log No. 119571  
Permit No. \_\_\_\_\_  
Basin 212

**PRINT OR TYPE ONLY  
DO NOT WRITE ON BACK**

*Please complete this form in its entirety in  
accordance with NRS 534.170 and NAC 534.340*

NOTICE OF INTENT NO. 37186

1 OWNER Faverman-Kenyon Trust & Beyer Kenyounjudith trs ADDRESS AT WELL LOCATION 5252 Harris Ave  
MAILING ADDRESS 5252 Harris ave Las Vegas NV  
Subdivision Name: \_\_\_\_\_ County: Clark

2 LOCATION NW 1/4 SW 1/4 Sec 28 T 20S N/S R 62 E Latitude 36.178329 UTM E  NAD 27  
PERMIT/WAIVER No. 140-28-303-006 Longitude -115.058376 N  NAD 83/WGS 84  
Issued by Water Resources Parcel No.

3 TYPE OF WELL  
 Domestic  Irrigation  Test  
 Municipal/Industrial  Monitor  Stock  
Is this well being plugged because a replacement well was drilled? \_\_\_\_\_  
If yes, what is replacement well NOI? \_\_\_\_\_  
Is there an existing well log? yes  
If yes, what is NDWR well log #? 57137

4 EXISTING WELL CONSTRUCTION  
Depth Drilled 120 Feet Depth Cased 120 Feet  
EXISTING CASING SCHEDULE

Size O.D. (Inches)	Weight/Ft. (Pounds)	Wall Thickness (Inches)	From (Feet)	To (Feet)
<u>85/8</u>	<u>12.2</u>	<u>10 ga.</u>	<u>0</u>	<u>120</u>

7 WELL PLUGGING PROCEDURE  
Was well cleaned out to total depth?  yes  no  
If well was not cleaned out to total depth, please explain why: \_\_\_\_\_  
Was the well contaminated?  yes  no  
Was the casing pulled?  yes  no  
Was the casing over drilled?  yes  no  
If casing was left in place, please show where additional perforations were made:  
Additional Perforations:

Existing Perforations:  
Type of perforation torch  
Size of perforation 1/4x6 4 a rovd

From	feet to	feet	feet
<u>60</u>	<u>120</u>		

Type of perforator used: 1/4 x3

From	feet to	feet	Number of perfs per linear foot
<u>45</u>	<u>109</u>		<u>4</u>

5 WATER LEVEL  
Static water level 25 feet below land surface  
Artesian flow  G.P.M. \_\_\_\_\_ P.S.I. \_\_\_\_\_  
Water temperature \_\_\_\_\_ °F Quality \_\_\_\_\_

8 WELL PLUGGING MATERIALS

From	feet to	feet	Material Used
<u>0</u>	<u>109</u>		<input checked="" type="checkbox"/> Pumped <input type="checkbox"/> Poured
			<input type="checkbox"/> Pumped <input type="checkbox"/> Poured
			<input type="checkbox"/> Pumped <input type="checkbox"/> Poured
			<input type="checkbox"/> Pumped <input type="checkbox"/> Poured
			<input type="checkbox"/> Pumped <input type="checkbox"/> Poured

6 Additional Notes or Comments  
\_\_\_\_\_

tremied  
filled from botton  
to top with cement grout

DCNR/DWR/SNB  
RECEIVED  
FEB 21 2014

Neat Cement Fluid Weight 70sk sand lbs/gal  
Bentonite Grout \_\_\_\_\_ % bentonite  
Date Started 2/19/2014  
Date Completed 2/19/2014

9 DRILLER'S CERTIFICATION  
This well was plugged and abandoned under my supervision and the report is true to the best of my knowledge.  
Name Eagle Drilling LLC. Contractor  
Address 7150 Placid St., Las Vegas, Nv., 89119 Contractor  
Nevada contractor's license number 51266  
issued by the State Contractor's Board  
Nevada driller's license number issued by the 2097  
Division of Water Resources, the on-site driller  
Signed \_\_\_\_\_  
By driller performing actual drilling on site or contractor  
Date 2/20/2014