

STATE OF NEVADA
DIVISION OF WATER RESOURCES
WELL DRILLER'S PLUGGING REPORT

OFFICE USE ONLY
Log No. 120058
Permit No. _____
Basin 109

PRINT OR TYPE ONLY
DO NOT WRITE ON BACK

Please complete this form in its entirety in accordance with NRS 534.170 and NAC 534.340

NOTICE OF INTENT NO. 69884
WELL NAME (If applicable): DW-29

1 OWNER A & A Construction ADDRESS AT WELL LOCATION Heybourne Lane in the Ranch at Gardnerville development
MAILING ADDRESS P.O. Box 995 Minden, NV. 89423 Subdivision Name: Ranch at Gardnerville County: Douglas

2 LOCATION SW 1/4 NW 1/4 Sec 33 T 13N N/S R 20 E Latitude 38 56.906 N UTM E NAD 27
PERMIT/WAIVER No. DEW 71 Longitude 119 44.943 W N NAD 83/WGS 84

issued by Water Resources Parcel No. _____

3 TYPE OF WELL
 Domestic Irrigation Test
 Municipal/Industrial Monitor Stock

Is this well being plugged because a replacement well was drilled? no
If yes, what is replacement well NOI? _____

Is there an existing well log? yes
If yes, what is NDWR well log #? 106281

4 EXISTING WELL CONSTRUCTION
Depth Drilled 20 Feet Depth Cased 20 Feet

EXISTING CASING SCHEDULE

Size O.D. (Inches)	Weight/Ft. (Pounds)	Wall Thickness (Inches)	From (Feet)	To (Feet)
10	8.68	.413	0	20

Existing Perforations:
Type of perforation hand slotted
Size of perforation 0.25

From	feet to	feet
From _____	feet to _____	feet
From _____	feet to _____	feet
From _____	feet to _____	feet
From _____	feet to _____	feet
From _____	feet to _____	feet

5 WATER LEVEL
Static water level 6.6' feet below land surface
Artesian flow _____ G.P.M. _____ P.S.I.
Water temperature _____ °F Quality _____

6 Additional Notes or Comments
Measured well depth at 20'. Installed 19' of 2" tremie pipe. Pumped in approx. 13 cu. ft. of neat cement from bottom of well to surface. Pulled casing and topped of hole after casing was removed.

Plugs well log 106281
Nad 27
38.944356 N
119.449050 W

2014.02.20 11:15 AM
2014.02.20 11:15 AM

7 WELL PLUGGING PROCEDURE
Was well cleaned out to total depth? yes no
If well was not cleaned out to total depth, please explain why: _____

Was the well contaminated? yes no
Was the casing pulled? yes no If pulled from: 0 feet to 20 feet
Was the casing over drilled? yes no
If casing was left in place, please show where additional perforations were made:
Additional Perforations:
Type of perforator used:
From _____ feet to _____ feet Number of perfs per linear foot _____
From _____ feet to _____ feet Number of perfs per linear foot _____
From _____ feet to _____ feet Number of perfs per linear foot _____
From _____ feet to _____ feet Number of perfs per linear foot _____
From _____ feet to _____ feet Number of perfs per linear foot _____
From _____ feet to _____ feet Number of perfs per linear foot _____
From _____ feet to _____ feet Number of perfs per linear foot _____
From _____ feet to _____ feet Number of perfs per linear foot _____
From _____ feet to _____ feet Number of perfs per linear foot _____
From _____ feet to _____ feet Number of perfs per linear foot _____
From _____ feet to _____ feet Number of perfs per linear foot _____
From _____ feet to _____ feet Number of perfs per linear foot _____

8 WELL PLUGGING MATERIALS
Material Used
From 0 feet to 20 feet neat cement Pumped Poured
From _____ feet to _____ feet Pumped Poured
Neat Cement Fluid Weight 14.6 lbs/gal
Bentonite Grout _____ % bentonite
Date Started 2/24/2014
Date Completed 2/24/2014

9 DRILLER'S CERTIFICATION
This well was plugged and abandoned under my supervision and the report is true to the best of my knowledge.
Name Carson Pump, LLC
Contractor
Address P.O. Box 20159
Contractor
Carson City, NV. 89721
Nevada contractor's license number _____
issued by the State Contractor's Board 39920A
Nevada driller's license number issued by the Division of Water Resources, the on-site driller 1482
Signed [Signature]
By driller performing actual drilling on site or contractor
Date 3/21/2014