

**STATE OF NEVADA  
DIVISION OF WATER RESOURCES  
WELL DRILLER'S PLUGGING REPORT**

**OFFICE USE ONLY**  
Log No. 120208  
Permit No. \_\_\_\_\_  
Basin 312

**PRINT OR TYPE ONLY  
DO NOT WRITE ON BACK**

*Please complete this form in its entirety in  
accordance with NRS 534.170 and NAC 534.340*

NOTICE OF INTENT NO. 37147

1 OWNER Clark County (Pk & Comm Serv) ADDRESS AT WELL LOCATION 5483 Club House Drive  
MAILING ADDRESS 500 South Grand Central Pkwy, 2nd Floor  
Las Vegas, NV Subdivision Name: \_\_\_\_\_ County: Clark

2 LOCATION NE  $\frac{1}{4}$  NE  $\frac{1}{4}$  Sec 9 T 21S N/S R 62 E Latitude 36.141415 UTM E  NAD 27  
PERMIT/WAIVER No. DW-1337 16109501001 Longitude -115.051726 N  NAD 83/WGS 84  
Issued by Water Resources Parcel No.

3 TYPE OF WELL  Domestic  Irrigation  Test  Municipal/Industrial  Monitor  Stock  
Is this well being plugged because a replacement well was drilled? no  
If yes, what is replacement well NOI? \_\_\_\_\_  
Is there an existing well log? yes  
If yes, what is NDWR well log #? N/A

4 EXISTING WELL CONSTRUCTION  
Depth Drilled 50 Feet Depth Cased 50 Feet  
EXISTING CASING SCHEDULE

Size O.D. (Inches)	Weight/Ft. (Pounds)	Wall Thickness (Inches)	From (Feet)	To (Feet)
<u>8</u>	<u>6</u>	<u>3/8</u>	<u>0</u>	<u>50</u>

7 WELL PLUGGING PROCEDURE  
Was well cleaned out to total depth?  yes  no  
If well was not cleaned out to total depth, please explain why: \_\_\_\_\_  
Was the well contaminated?  yes  no  
Was the casing pulled?  yes  no  
Was the casing over drilled?  yes  no  
If casing was left in place, please show where additional perforations were made: \_\_\_\_\_

Existing Perforations:  
Type of perforation machine  
Size of perforation 0.32

From	feet to	feet
<u>30</u>	<u>50</u>	<u>feet</u>

Additional Perforations:  
Type of perforator used: \_\_\_\_\_

From	feet to	feet	Number of perfs per linear foot

5 WATER LEVEL  
Static water level \_\_\_\_\_ feet below land surface  
Artesian flow \_\_\_\_\_ G.P.M. \_\_\_\_\_ P.S.I.  
Water temperature \_\_\_\_\_ ° F Quality \_\_\_\_\_

8 WELL PLUGGING MATERIALS

From	feet to	feet	Material Used	<input type="checkbox"/> Pumped	<input checked="" type="checkbox"/> Poured
<u>2</u>	<u>12</u>	<u>feet</u>	<u>Concrete Grout</u>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
				<input type="checkbox"/>	<input type="checkbox"/>
				<input type="checkbox"/>	<input type="checkbox"/>
				<input type="checkbox"/>	<input type="checkbox"/>
				<input type="checkbox"/>	<input type="checkbox"/>
				<input type="checkbox"/>	<input type="checkbox"/>

6 Additional Notes or Comments  
DW #16  
UNRECOVERED  
APR 5 2014

Neat Cement Fluid Weight \_\_\_\_\_ lbs/gal  
Bentonite Grout \_\_\_\_\_ % bentonite  
Date Started 2/20/2014  
Date Completed 2/20/2014

9 DRILLER'S CERTIFICATION  
This well was plugged and abandoned under my supervision and the report is true to the best of my knowledge.  
Name Viking Drillers Inc Contractor  
Address 5950 Granite Lake Drive Contractor  
Granite Bay, CA 95746  
Nevada contractor's license number issued by the State Contractor's Board 0034680  
Nevada driller's license number issued by the Division of Water Resources, the on-site driller DW-2361  
Signed \_\_\_\_\_  
By driller performing actual plugging on site or contractor  
Date 3/28/2014