

THIS BORING LOG IS FOR VIKING'S INTERNAL PURPOSES ONLY. IT DOES NOT REPRESENT INFORMATION PROVIDED BY A SOILS ENGINEER.

LOG FOR BORING NO. <u>105, 106</u>		JOB NAME: <u>LV Paving</u>			
DATE STARTED <u>1-10-14</u>	DATE COMPLETED	LOGGED BY <u>Ed</u>	DRILLED BY <u>Ed</u>	TYPE OF DRILL RIG <u>#32</u>	JOB NO. <u>6/50</u>
DEPTH OF HOLE <u>50'</u>	DIAMETER OF HOLE <u>24"</u>	CASING <u>8"</u>	PERFORATIONS <u>20'</u>	SAMPLING METHOD	ELEVATION
LOCATION <u>#105</u> <u>Sta 14+40</u>				# <u>106</u> <u>13+80</u>	
DEPTH				DRILLERS NOTES:	
	SAMPLES	GRAPHIC	DESCRIPTION		
0'			silty backfill		
			silty clay		
10'		▽			
20'			Kleechi Red silty clay		
30'					
40'			cemented gravel Red silty clay		
50'					
60'					
70'					
80'					
90'					
100'					

Kleechi layer was not as thick.

DCNR/DWR/SNBO
RECEIVED
AUG 12 2014

REVIEWED
By spilliber at 4:36 pm, Jan 21, 2014