

STATE OF NEVADA  
DIVISION OF WATER RESOURCES  
WELL DRILLER'S PLUGGING REPORT

OFFICE USE ONLY  
Log No. 120810  
Permit No. \_\_\_\_\_  
Basin 212

PRINT OR TYPE ONLY  
DO NOT WRITE ON BACK

Please complete this form in its entirety in  
accordance with NRS 534.170 and NAC 534.340

1 OWNER Colony Resorts LVH Acquisitions % Rschaffhauser ADDRESS AT WELL LOCATION 3000 Paradise RD Las Vegas NV  
MAILING ADDRESS 63000 Paradise RD Las Vegas NV 89109

NOTICE OF INTENT NO. 36559

2 LOCATION NE 1/4 SW 1/4 Sec 10 T 21S N/S R 61 E Latitude 36.08.03.13 UTM E  NAD 27  
PERMIT/WAIVER No. 162-10-302-007 Longitude 115.0857.23 N  NAD 83/WGS 84  
Issued by Water Resources Parcel No. \_\_\_\_\_

3 TYPE OF WELL  
 Domestic  Irrigation  Test  
 Municipal/Industrial  Monitor  Stock  
Is this well being plugged because a replacement well was drilled? no  
If yes, what is replacement well NOI? \_\_\_\_\_  
Is there an existing well log? yes  
If yes, what is NDWR well log #? 115773

4 EXISTING WELL CONSTRUCTION  
Depth Drilled 20 Feet Depth Cased 19 Feet

EXISTING CASING SCHEDULE

Size O.D. (Inches)	Weight/Ft. (Pounds)	Wall Thickness (Inches)	From (Feet)	To (Feet)
<u>2</u>	<u>pvc</u>	<u>sch 40</u>	<u>0</u>	<u>19</u>

7 WELL PLUGGING PROCEDURE  
Was well cleaned out to total depth?  yes  no  
If well was not cleaned out to total depth, please explain why: \_\_\_\_\_  
Was the well contaminated?  yes  no  
Was the casing pulled?  yes  no  
Was the casing over drilled?  yes  no  
If casing was left in place, please show where additional perforations were made:  
Additional Perforations:  
Type of perforator used: \_\_\_\_\_

Existing Perforations:

Type of perforation	slotted screen
Size of perforation <u>4</u>	0.02
From _____ feet to _____ feet	<u>19</u> feet
From _____ feet to _____ feet	_____ feet
From _____ feet to _____ feet	_____ feet
From _____ feet to _____ feet	_____ feet

Additional Perforations:

From _____ feet to _____ feet	Type of perforator used: _____	Number of perfs per linear foot _____
From _____ feet to _____ feet	_____	_____
From _____ feet to _____ feet	_____	_____
From _____ feet to _____ feet	_____	_____
From _____ feet to _____ feet	_____	_____
From _____ feet to _____ feet	_____	_____

5 WATER LEVEL  
Static water level 3 feet below land surface  
Artesian flow \_\_\_\_\_ G.P.M. \_\_\_\_\_ P.S.I.  
Water temperature \_\_\_\_\_ °F Quality \_\_\_\_\_

8 WELL PLUGGING MATERIALS

From _____ feet to _____ feet	Material Used	<input type="checkbox"/> Pumped	<input checked="" type="checkbox"/> Poured
From <u>0</u> feet to _____ feet	bentonite	<input type="checkbox"/>	<input checked="" type="checkbox"/>
From _____ feet to _____ feet	chips	<input type="checkbox"/>	<input type="checkbox"/>
From _____ feet to _____ feet	_____	<input type="checkbox"/>	<input type="checkbox"/>
From _____ feet to _____ feet	_____	<input type="checkbox"/>	<input type="checkbox"/>
From _____ feet to _____ feet	_____	<input type="checkbox"/>	<input type="checkbox"/>

6 Additional Notes or Comments  
\_\_\_\_\_  
\_\_\_\_\_  
casing was pulled  
and backfilled with bentonite chips  
\_\_\_\_\_  
\_\_\_\_\_  
well 2  
DCNR/DWR/SNBO  
RECEIVED  
JUL 15 2014

Neat Cement Fluid Weight \_\_\_\_\_ lbs/gal  
Bentonite Grout \_\_\_\_\_ % bentonite  
Date Started 10/24/2012  
Date Completed 10/24/2012

9 DRILLER'S CERTIFICATION  
This well was plugged and abandoned under my supervision and the report is true to the best of my knowledge.  
Name Eagle Drilling Services llc Contractor  
Address 7150 placid street Contractor  
Las Vegas Nv 89119  
Nevada contractor's license number \_\_\_\_\_  
issued by the State Contractor's Board 51266  
Nevada driller's license number issued by the \_\_\_\_\_  
Division of Water Resources, the on-site driller 2097  
Signed \_\_\_\_\_  
By driller performing actual drilling on site or contractor  
Date 7/11/2014