

**STATE OF NEVADA
DIVISION OF WATER RESOURCES
WELL DRILLER'S PLUGGING REPORT**

OFFICE USE ONLY
Log No. 120812
Permit No. _____
Basin 212

**PRINT OR TYPE ONLY
DO NOT WRITE ON BACK**

*Please complete this form in its entirety in
accordance with NRS 534.170 and NAC 534.340*

NOTICE OF INTENT NO. 36557

1 OWNER Colony Resorts LVH Acquisitions % Rschaffhauser ADDRESS AT WELL LOCATION 3000 Parradise RD Las Vegas NV
MAILING ADDRESS 63000Paradise RD Las Vegas NV 89109

Subdivision Name: _____ County: Clark
2 LOCATION NW ¼ SW ¼ Sec 10 T 21S N/S R 61 E Latitude 36.08.02.24 UTM E NAD 27
PERMIT/WAIVER No. 162-10-302-007 Longitude 115.09.14.44 N NAD 83/WGS 84
Issued by Water Resources Parcel No.

3 TYPE OF WELL
 Domestic Irrigation Test
 Municipal/Industrial Monitor Stock
Is this well being plugged because a replacement well was drilled? no
If yes, what is replacement well NOI? _____
Is there an existing well log? yes
If yes, what is NDWR well log #? 115775

4 EXISTING WELL CONSTRUCTION
Depth Drilled 34 Feet Depth Cased 30 Feet

EXISTING CASING SCHEDULE

Size O.D. (Inches)	Weight/Ft. (Pounds)	Wall Thickness (Inches)	From (Feet)	To (Feet)
<u>2</u>	<u>pvc</u>	<u>sch 40</u>	<u>0</u>	<u>30</u>

Existing Perforations:
Type of perforation slotted screen
Size of perforation 0.02
From 15 feet to 30 feet
From _____ feet to _____ feet
From _____ feet to _____ feet
From _____ feet to _____ feet

5 WATER LEVEL
Static water level 18 feet below land surface
Artesian flow _____ G.P.M. _____ P.S.I.
Water temperature _____ °F Quality _____

6 Additional Notes or Comments

casing was pulled

and backfield with bentonite chips

well 1

**DCNR/DWR/SNBO
RECEIVED
JUL 15 2014**

7 WELL PLUGGING PROCEDURE
Was well cleaned out to total depth? yes no
If well was not cleaned out to total depth, please explain why: _____

Was the well contaminated? yes no
Was the casing pulled? yes no
Was the casing over drilled? yes no
If casing was left in place, please show where additional perforations were made:
Additional Perforations:

Type of perforater used:
From _____ feet to _____ feet Number of perfs per linear foot _____
From _____ feet to _____ feet Number of perfs per linear foot _____
From _____ feet to _____ feet Number of perfs per linear foot _____
From _____ feet to _____ feet Number of perfs per linear foot _____
From _____ feet to _____ feet Number of perfs per linear foot _____
From _____ feet to _____ feet Number of perfs per linear foot _____

8 WELL PLUGGING MATERIALS
Material Used
From 0 feet to _____ feet bentonite Pumpe Poured
From _____ feet to _____ feet chipe Pumped Poured
From _____ feet to _____ feet _____ Pumped Poured
From _____ feet to _____ feet _____ Pumped Poured
From _____ feet to _____ feet _____ Pumped Poured
From _____ feet to _____ feet _____ Pumped Poured

Neat Cement Fluid Weight _____ lbs/gal
Bentonite Grout _____ % bentonite
Date Started 10/24/2012
Date Completed 10/24/2012

9 DRILLER'S CERTIFICATION
This well was plugged and abandoned under my supervision and the report is true to the best of my knowledge.
Name Eagle Drilling Services llc Contractor
Address 7150 placid street Contractor
Las Vegas Nv 89119
Nevada contractor's license number _____ issued by the State Contractor's Board 51266
Nevada driller's license number issued by the Division of Water Resources life on-site driller 2097
Signed _____
By driller performing actual drilling on site or contractor
Date 7/11/2014

USE ADDITIONAL SHEETS IF NECESSARY

36.1339843 NAD
-115.1531781 27

(Rev. 05-05)