

**STATE OF NEVADA  
DIVISION OF WATER RESOURCES  
WELL DRILLER'S PLUGGING REPORT**

OFFICE USE ONLY  
Log No. 121225  
Permit No. \_\_\_\_\_  
Basin \_\_\_\_\_

**PRINT OR TYPE ONLY  
DO NOT WRITE ON BACK**

*Please complete this form in its entirety in  
accordance with NRS 534.170 and NAC 534.340*

NOTICE OF INTENT NO. 71430

1 OWNER County of Clark (PK & Comm Serv) ADDRESS AT WELL LOCATION 5483 Clubhouse Dr  
MAILING ADDRESS 500 S. Grand Central Pkwy  
Las Vegas, NV 89155 Subdivision Name: \_\_\_\_\_ County: \_\_\_\_\_

2 LOCATION NW 1/4 NE 1/4 1/4 Sec 9 T 21S N/SR 62 E Latitude UTME 812488.5  NAD 27  
PERMIT/WAIVER No. DW-1334A 16109501001 Longitude N 26 753210.5  NAD 83/WGS 84  
*Issued by Water Resources Parcel No.* State Plane

3 TYPE OF WELL  Domestic  Irrigation  Test  Municipal/Industrial  Monitor  Stock  
Is this well being plugged because a replacement well was drilled? no  
If yes, what is replacement well NOI? \_\_\_\_\_  
Is there an existing well log? \_\_\_\_\_  
If yes, what is NDWR well log #? \_\_\_\_\_

4 EXISTING WELL CONSTRUCTION  
Depth Drilled 50 Feet Depth Cased 50 Feet

EXISTING CASING SCHEDULE				
Size O.D. (Inches)	Weight/Ft. (Pounds)	Wall Thickness (Inches)	From (Feet)	To (Feet)
8	6	3/8	0	50

Existing Perforations:

Type of perforation	Size of perforation	From	To
<u>machine slotted</u>	<u>0.032</u>	<u>50</u>	<u>feet</u>

7 WELL PLUGGING PROCEDURE  
Was well cleaned out to total depth?  yes  no  
If well was not cleaned out to total depth, please explain why: \_\_\_\_\_

Was the well contaminated?  yes  no  
Was the casing pulled?  yes  no  
Was the casing over drilled?  yes  no  
If casing was left in place, please show where additional perforations were made:  
Additional Perforations:  
Type of perforator used: \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_

5 WATER LEVEL  
Static water level \_\_\_\_\_ feet below land surface  
Artesian flow \_\_\_\_\_ G.P.M. P.S.I.  
Water temperature \_\_\_\_\_ ° F Quality \_\_\_\_\_

8 WELL PLUGGING MATERIALS

From	To	Material Used	Pumped	Poured
<u>2</u>	<u>10</u>	<u>concrete grout</u>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
<u>10</u>	<u>12</u>	<u>benonite chips</u>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
			<input type="checkbox"/>	<input type="checkbox"/>
			<input type="checkbox"/>	<input type="checkbox"/>
			<input type="checkbox"/>	<input type="checkbox"/>
			<input type="checkbox"/>	<input type="checkbox"/>

6 Additional Notes or Comments  
LVP Well #211  
RECEIVED  
SEP 29 2014

Neat Cement Fluid Weight 94/7 lbs/gal  
Bentonite Grout \_\_\_\_\_ % bentonite  
Date Started 8/14/2014  
Date Completed 8/14/2014

9 DRILLER'S CERTIFICATION  
This well was plugged and abandoned under my supervision and the report is true to the best of my knowledge.  
Name Viking Drillers Inc Contractor  
Address 5950 Granite Lake Dr. Contractor  
Granite Bay, CA 95691  
Nevada contractor's license number \_\_\_\_\_  
issued by the State Contractor's Board 0034680  
Nevada driller's license number issued by the \_\_\_\_\_  
Division of Water Resources, the on-site driller DW-2361  
Signed [Signature]  
By driller performing actual plugging on site or contractor  
Date 7/31/2014