

**STATE OF NEVADA  
DIVISION OF WATER RESOURCES  
WELL DRILLER'S PLUGGING REPORT**

**OFFICE USE ONLY**  
Log No. 121262  
Permit No. \_\_\_\_\_  
Basin \_\_\_\_\_

**PRINT OR TYPE ONLY  
DO NOT WRITE ON BACK**

*Please complete this form in its entirety in  
accordance with NRS 534.170 and NAC 534.340*

NOTICE OF INTENT NO. 37150

1 OWNER County of Clark (PK & Comm Serv)  
MAILING ADDRESS 500 S. Grand Central Pkwy  
Las Vegas, NV 89155

ADDRESS AT WELL LOCATION 5483 Clubhouse Dr  
Subdivision Name: \_\_\_\_\_ County: \_\_\_\_\_

2 LOCATION SW  $\frac{1}{4}$  SE  $\frac{1}{4}$  Sec 4 T 21S N/S R 62 E  
PERMIT/WAIVER No. DW-1335 16104701002  
Issued by Water Resources Parcel No.

Latitude \_\_\_\_\_ UTM 812802.1  NAD 27  
Longitude \_\_\_\_\_ N 26754722.5  NAD 83/WGS 84  
State Plane

3 TYPE OF WELL  
 Domestic  Irrigation  Test  
 Municipal/Industrial  Monitor  Stock

Is this well being plugged because a replacement well was drilled? no  
If yes, what is replacement well NOI? \_\_\_\_\_  
Is there an existing well log? \_\_\_\_\_  
If yes, what is NDWR well log #? \_\_\_\_\_

4 EXISTING WELL CONSTRUCTION  
Depth Drilled 50 Feet Depth Cased 50 Feet

7 WELL PLUGGING PROCEDURE  
Was well cleaned out to total depth?  yes  no  
If well was not cleaned out to total depth, please explain why: \_\_\_\_\_

EXISTING CASING SCHEDULE				
Size O.D. (Inches)	Weight/Ft. (Pounds)	Wall Thickness (Inches)	From (Feet)	To (Feet)
8	6	3/8	0	50

Was the well contaminated?  yes  no  
Was the casing pulled?  yes  no  
Was the casing over drilled?  yes  no  
If casing was left in place, please show where additional perforations were made:  
Additional Perforations:

Existing Perforations:

From	Type of perforation	Size of perforation	feet to	feet
	machine slotted	0.032		
From		30	feet to	50
From			feet to	
From			feet to	
From			feet to	
From			feet to	

Type of perforater used:

From	feet to	feet	Number of perfs per linear foot
From			

5 WATER LEVEL  
Static water level \_\_\_\_\_ feet below land surface  
Artesian flow \_\_\_\_\_ G.P.M. \_\_\_\_\_ P.S.I.  
Water temperature \_\_\_\_\_ °F Quality \_\_\_\_\_

8 WELL PLUGGING MATERIALS

From	feet to	feet	Material Used	Pumped	Poured
From	2	feet to	10	feet concrete grout	<input type="checkbox"/> Pumped <input checked="" type="checkbox"/> Poured
From	10	feet to	12	feet bentonite chips	<input type="checkbox"/> Pumped <input checked="" type="checkbox"/> Poured
From		feet to			<input type="checkbox"/> Pumped <input type="checkbox"/> Poured
From		feet to			<input type="checkbox"/> Pumped <input type="checkbox"/> Poured
From		feet to			<input type="checkbox"/> Pumped <input type="checkbox"/> Poured
From		feet to			<input type="checkbox"/> Pumped <input type="checkbox"/> Poured

6 Additional Notes or Comments  
  
LVP Well #29  
  
DW-1335  
16104701002  
7/31/2014

Neat Cement Fluid Weight 94/7 lbs/gal  
Bentonite Grout \_\_\_\_\_ % bentonite  
Date Started 3/21/2014  
Date Completed 3/21/2014

9 DRILLER'S CERTIFICATION  
This well was plugged and abandoned under my supervision and the report is true to the best of my knowledge.  
Name Viking Drillers Inc Contractor  
Address 5950 Granite Lake Dr. Contractor  
Granite Bay, CA 95691  
Nevada contractor's license number issued by the State Contractor's Board 0034680  
Nevada driller's license number issued by the Division of Water Resources, the on-site driller DW-2361  
Signed [Signature] By driller performing actual drilling on site or contractor  
Date 7/31/2014