

STATE OF NEVADA  
 DIVISION OF WATER RESOURCES  
**WELL DRILLER'S PLUGGING REPORT**

OFFICE USE ONLY  
 Log No. **121276**  
 Permit No. \_\_\_\_\_  
 Basin \_\_\_\_\_

PRINT OR TYPE ONLY  
 DO NOT WRITE ON BACK

Please complete this form in its entirety in  
 accordance with NRS 534.170 and NAC 534.340

NOTICE OF INTENT NO. **38006**

1 OWNER County of Clark (PK & Comm Serv) ADDRESS AT WELL LOCATION 5483 Clubhouse Dr  
 MAILING ADDRESS 500 S. Grand Central Pkwy  
Las Vegas, NV 89155 Subdivision Name: \_\_\_\_\_ County: \_\_\_\_\_

2 LOCATION SW ¼ NE ¼ Sec 4 T 21S N/S R 62 E Latitude UTM 811816.5  NAD 27  
 PERMIT/WAIVER No. DW-1339 16104201001 Longitude N 36.757576.3  NAD 83/WGS 84

Issued by Water Resources Parcel No. \_\_\_\_\_

3 TYPE OF WELL  
 Domestic  Irrigation  Test  
 Municipal/Industrial  Monitor  Stock

Is this well being plugged because a replacement well was drilled? no  
 If yes, what is replacement well NOI? \_\_\_\_\_

Is there an existing well log? \_\_\_\_\_  
 If yes, what is NDWR well log #? \_\_\_\_\_

4 EXISTING WELL CONSTRUCTION  
 Depth Drilled 50 Feet Depth Cased 50 Feet

EXISTING CASING SCHEDULE

Size O.D. (Inches)	Weight/Ft. (Pounds)	Wall Thickness (Inches)	From (Feet)	To (Feet)
8	6	3/8	0	50

7 WELL PLUGGING PROCEDURE  
 Was well cleaned out to total depth?  yes  no  
 If well was not cleaned out to total depth, please explain why: \_\_\_\_\_

Was the well contaminated?  yes  no  
 Was the casing pulled?  yes  no  
 Was the casing over drilled?  yes  no

If casing was left in place, please show where additional perforations were made:  
 Additional Perforations:

Existing Perforations:

Type of perforation	Size of perforation	From	feet to	feet
machine slotted	0.032	30	50	feet

Type of perforater used:

From	feet to	feet	Number of perfs per linear foot

5 WATER LEVEL  
 Static water level \_\_\_\_\_ feet below land surface  
 Artesian flow \_\_\_\_\_ G.P.M. \_\_\_\_\_ P.S.I.  
 Water temperature \_\_\_\_\_ °F Quality \_\_\_\_\_

8 WELL PLUGGING MATERIALS

6 Additional Notes or Comments

LVP Well #247

SEP 26 2012

From	feet to	feet	Material Used	<input type="checkbox"/> Pumped	<input checked="" type="checkbox"/> Poured
2	10	feet	concrete grout	<input type="checkbox"/>	<input checked="" type="checkbox"/>
10	12	feet	bentonite chips	<input type="checkbox"/>	<input checked="" type="checkbox"/>
		feet		<input type="checkbox"/>	<input type="checkbox"/>
		feet		<input type="checkbox"/>	<input type="checkbox"/>
		feet		<input type="checkbox"/>	<input type="checkbox"/>
		feet		<input type="checkbox"/>	<input type="checkbox"/>

Neat Cement Fluid Weight 94/7 lbs/gal  
 Bentonite Grout \_\_\_\_\_ % bentonite

Date Started 6/17/2014  
 Date Completed 6/17/2014

9 DRILLER'S CERTIFICATION  
 This well was plugged and abandoned under my supervision and the report is true to the best of my knowledge.

Name Viking Drillers Inc  
 Contractor

Address 5950 Granite Lake Dr.  
 Contractor

Granite Bay, CA 95691

Nevada contractor's license number \_\_\_\_\_  
 issued by the State Contractor's Board 0034680

Nevada driller's license number issued by the  
 Division of Water Resources, the on-site driller DW-2361

Signed \_\_\_\_\_  
 By driller performing actual drilling on site or contractor

Date 7/31/2014