STATE OF NEVADA
DIVISION OF WATER RESOURCES
WELL DRILLER'S PLUGGING REPORT

OFFICE USE ONLY
Log No. 121406
Permit No.
Basin

PRINT OR TYPE ONLY
DO NOT WRITE ON BACK

Please complete this form in its entirety in accordance with NRS 534.170 and NAC 534.340

NOTICE OF INTENT NO. 37222
WELL NAME (If applicable): ewx mcf-8

1 OWNER Titanium Metals Corporation
MAILING ADDRESS P.O.Box. 2128
Henderson, NV 89015

ADDRESS AT WELL LOCATION 181 N. Water St.
Henderson, NV 89015
Subdivision Name: County: Clark

2 LOCATION NE ¼ SE ¼ Sec 12 T 22S N/S R 62 E
PERMIT/WAIVER No. 178-12-701-002
Issued by Water Resources Parcel No.

Latitude 36.0485175
Longitude -114.9953605
UTM E 829973.06
N 26719806.70
☐ NAD 27
☒ NAD 83/WGS 8

3 TYPE OF WELL
☐ Domestic ☐ Irrigation ☐ Test
☐ Municipal/Industrial ☒ Monitor ☐ Stock

Is this well being plugged because a replacement well was drilled? No
If yes, what is replacement well NO!?

Is there an existing well log?
If yes, what is NDWR well log #?

4 EXISTING WELL CONSTRUCTION
Depth Drilled 52 Feet Depth Cased 52 Feet

EXISTING CASING SCHEDULE

Size O.D. (Inches)	Weight/Ft. (Pounds)	Wall Thickness (Inches)	From (Feet)	To (Feet)
4	PVC	SCH 80	0	52

Existing Perforations:
Type of perforation
Size of perforation
From feet to feet
From feet to feet
From feet to feet
From feet to feet
From feet to feet

5 WATER LEVEL
Static water level 28 feet below land surface
Artesian flow G.P.M. P.S.I
Water temperature °F Quality

6 Additional Notes or Comments

** Attempted to pull casing but was unsuccesful.
Knocked out bottom cap, and pour
hydrated bentonite chips.**

DCNR/DWR/SNBC
RECEIVED
JUL 25 2014

7 WELL PLUGGING PROCEDURE
Was well cleaned out to total depth? ☒ yes ☐ no
If well was not cleaned out to total depth, please explain why:

Was the well contaminated? ☐ yes ☒ no
Was the casing pulled? ☐ yes ☒ no If pulled from: feet to feet
Was the casing over drilled? ☐ yes ☒ no
If casing was left in place, please show where additional perforations were made:
Additional Perforations:
Type of perforater used:
From feet to feet Number of perfs per linear foot
From feet to feet Number of perfs per linear foot
From feet to feet Number of perfs per linear foot
From feet to feet Number of perfs per linear foot
From feet to feet Number of perfs per linear foot
From feet to feet Number of perfs per linear foot
From feet to feet Number of perfs per linear foot
From feet to feet Number of perfs per linear foot
From feet to feet Number of perfs per linear foot
From feet to feet Number of perfs per linear foot
From feet to feet Number of perfs per linear foot

8 WELL PLUGGING MATERIALS

From	feet to	Material Used		
From 0	feet to 52	Bentonite	☐ Pumped	☒ Poured
From	feet to		☐ Pumped	☐ Poured
From	feet to		☐ Pumped	☐ Poured
From	feet to		☐ Pumped	☐ Poured
From	feet to		☐ Pumped	☐ Poured
From	feet to		☐ Pumped	☐ Poured

Neat Cement Fluid Weight lbs/gal
Bentonite Grout % bentonite
Date Started 7/18/2014
Date Completed 7/18/2014

9 DRILLER'S CERTIFICATION
This well was plugged and abandoned under my supervision and the report is true to the best of my knowledge.
Name Eagle Drilling Services
Contractor
Address 7150 Placid St. Las Vegas, NV 89119
Contractor

Nevada contractor's license number issued by the *State Contractor's Board* 51266
Nevada driller's license number issued by the Division of Water Resources, the *on-site driller* 2490-LTD
Signed
By driller performing actual drilling on site or contractor
Date 7/18/2014

(Rev. 12-13)
USE ADDITIONAL SHEETS IF NECESSARY pg. of pg.

36.0485413 NAD27
-114.994534