

STATE OF NEVADA
 DIVISION OF WATER RESOURCES
WELL DRILLER'S PLUGGING REPORT

OFFICE USE ONLY
 Log No. 121726
 Permit No. 83203
 Basin _____

PRINT OR TYPE ONLY
 DO NOT WRITE ON BACK

Please complete this form in its entirety in accordance with NRS 534.170 and NAC 534.340

NOTICE OF INTENT NO. 72535

1. OWNER Esmeralda County ADDRESS AT WELL LOCATION Dyer Community Center
 MAILING ADDRESS 233 Crook St. Dyer, NV
Goldfield, NV 89013 Subdivision Name: _____ County: Esmeralda

2. LOCATION SW 1/4 NE 1/4 Sec 9 T3S / R35E Latitude 37.694555 UTM E _____ NAD 27
 PERMIT/WAIVER NO. R-1669,23976 007-281-06 Longitude -118.094244 N _____ NAD 83/WGS 84
 Issued by Water Resources 83203 Parcel No. _____

3. TYPE OF WELL _____ Is this well being plugged because a replacement well was drilled? Yes No
 Domestic Irrigation Test Monitor Stock
 Municipal/Industrial Stock If yes, what is replacement well NOI? 72534 Is there an existing well log? Yes No
 If yes, what is NDWR well log #? 18957

4. EXISTING WELL CONSTRUCTION
 Depth Drilled 200 Feet Depth Cased 200 Feet

EXISTING CASING SCHEDULE

Size O.D. (Inches)	Weight/Ft. (Pounds)	Wall Thickness (Inches)	From (Feet)	To (Feet)
12.75	33.41	.250	0	200

Existing Perforations:
 Type of perforation Machine Cut
 Size of perforation 3/16 x 10 rows

From <u>96</u> feet to <u>194</u> feet
From _____ feet to _____ feet
From _____ feet to _____ feet
From _____ feet to _____ feet
From _____ feet to _____ feet

5. WATER LEVEL
 Static water level: 136 feet below land surface
 Artesian flow: _____ G.P.M. _____ P.S.I.
 Water Temperature: _____ °F Quality _____

6. Additional Notes or Comments
We abandoned this well after removing the existing pump and pipe from the well. We used approximately 240 sacks of bentonite chips and approximately 30 sacks of neat cement. This well was identified as a Recreational/Domestic Well.

7. WELL PLUGGING PROCEDURE
 Was well cleaned out to total depth? Yes No
 If well was not cleaned out to total depth, please explain why: _____

Was the well contaminated? Yes No
 Was the casing pulled? Yes No
 Was the casing over drilled? Yes No
 If casing was left in place, please show where additional perforations were made:
 Additional Perforations: _____
 Type of perforator used: None -

From _____ feet to _____ feet	Number of perfs per linear foot _____
From _____ feet to _____ feet	Number of perfs per linear foot _____
From _____ feet to _____ feet	Number of perfs per linear foot _____
From _____ feet to _____ feet	Number of perfs per linear foot _____
From _____ feet to _____ feet	Number of perfs per linear foot _____
From _____ feet to _____ feet	Number of perfs per linear foot _____

8. WELL PLUGGING MATERIALS

Material Used

From	To	Material	Pumped	Poured
From <u>0</u> feet to <u>20</u> feet		Neat Cement	<input type="checkbox"/>	<input checked="" type="checkbox"/>
From <u>20</u> feet to <u>190</u> feet		Bentonit	<input type="checkbox"/>	<input checked="" type="checkbox"/>
From _____ feet to _____ feet			<input type="checkbox"/>	<input type="checkbox"/>
From _____ feet to _____ feet			<input type="checkbox"/>	<input type="checkbox"/>
From _____ feet to _____ feet			<input type="checkbox"/>	<input type="checkbox"/>
From _____ feet to _____ feet			<input type="checkbox"/>	<input type="checkbox"/>

Neat Cement Fluid Weight 15.0 lbs/gal
 Bentonite Grout >30 % bentonite

Date Started 1/20/15
 Date Completed 1/20/15

9. DRILLER'S CERTIFICATION

This well was plugged and abandoned under my supervision and the report is true to the best of my knowledge.

Name Bruce MacKay Pump & Well Service, Inc.
 (CONTRACTOR)

Address 1600 Mt. Rose Hwy
 (CONTRACTOR)

Reno, NV 89511

Nevada contractor's license number issued by the State Contractor's Board 23096

Nevada driller's license number issued by the Division of Water Resources, the on-site driller 1790

Signed R. Bruce MacKay
 By driller performing actual drilling on site or contractor

Date 1/21/15

DCNR/DWR/SNBO
 RECEIVED
 FEB 09 2015

(Rev 05-08)

USE ADDITIONAL SHEETS IF NECESSARY

NAD 27 37.694555
 -118.094244