

Well log#
121762



Stantec Consulting Services Inc.
1165 East Jennings Way, Suite 101
Elko, NV 89801-7977
Tel: (775) 738-8766
Fax: (775) 738-2264

595 Double Eagle Court, Suite 2000
Reno, NV 89521-9005
Tel: (775) 747-5777
Fax: (775) 747-2177

**Valmy Power Plant
Summary Log of Replacement Monitoring Well**

LF-3RR: Completed 02/03/2015

Well Number	From	To	Interval	Lithology	Groundwater
LF-3RR	0	3	3	Poorly graded sand	--
	3	33	30	Silty sand with minor gravel and clay beds	--
	33	38.5	5.5	Clayey sand	--
	38.5	50	11.5	Silt with sand	--
	50	68	18	Lean clay with sand lenses	--
	68	71	3	Clayey gravel with sand	Water at 68 feet
	71	80	9	Basalt and eruptive breccias	--

Notes: All intervals in feet below ground surface.
Groundwater depth as first encountered in drilling.



Walter M. Martin
Walter Martin, CPG-11358

2/11/15
Date

RECEIVED
2015 FEB 13 AM 11:23
STATE ENGINEERS OFFICE