

STATE OF NEVADA  
DIVISION OF WATER RESOURCES  
WELL DRILLER'S PLUGGING REPORT

OFFICE USE ONLY  
Log No. 121815  
Permit No. \_\_\_\_\_  
Basin \_\_\_\_\_

PRINT OR TYPE ONLY  
DO NOT WRITE ON BACK

Please complete this form in its entirety in  
accordance with NRS 534.170 and NAC 534.340

NOTICE OF INTENT NO. 37149

1 OWNER County of Clark (PK & Comm Serv) ADDRESS AT WELL LOCATION 5483 Clubhouse Dr  
MAILING ADDRESS 500 S. Grand Central Pkwy  
Las Vegas, NV 89155 Subdivision Name: \_\_\_\_\_ County: \_\_\_\_\_

2 LOCATION NW ¼ SE ¼ Sec 4 T 21S N/S/R 62 E Latitude 37° 06' 12.379.7  NAD 27  
PERMIT/WAIVER No. DW-1340 16104701002 Longitude 115° 06' 756674.9  NAD 83/WGS 84  
Issued by Water Resources Parcel No. State Plane

3 TYPE OF WELL  
 Domestic  Irrigation  Test  
 Municipal/Industrial  Monitor  Stock  
Is this well being plugged because a replacement well was drilled? no  
If yes, what is replacement well NOI? \_\_\_\_\_  
Is there an existing well log? \_\_\_\_\_  
If yes, what is NDWR well log #? \_\_\_\_\_

4 EXISTING WELL CONSTRUCTION  
Depth Drilled 50 Feet Depth Cased 50 Feet

EXISTING CASING SCHEDULE

Size O.D. (Inches)	Weight/Ft. (Pounds)	Wall Thickness (Inches)	From (Feet)	To (Feet)
8	6	3/8	0	50

Existing Perforations:

Type of perforation	Size of perforation	From	To
machine slotted	0.032	30	50

5 WATER LEVEL  
Static water level \_\_\_\_\_ feet below land surface  
Artesian flow \_\_\_\_\_ G.P.M. \_\_\_\_\_ P.S.I.  
Water temperature \_\_\_\_\_ °F Quality \_\_\_\_\_

6 Additional Notes or Comments  
  
LVP Well #147  
  
RECEIVED  
SEP 28 2014

7 WELL PLUGGING PROCEDURE  
Was well cleaned out to total depth?  yes  no  
If well was not cleaned out to total depth, please explain why: \_\_\_\_\_

Was the well contaminated?  yes  no  
Was the casing pulled?  yes  no  
Was the casing over drilled?  yes  no

If casing was left in place, please show where additional perforations were made:  
Additional Perforations:  
Type of perforator used: \_\_\_\_\_

From	feet to	feet	Number of perfs per linear foot

8 WELL PLUGGING MATERIALS

From	feet to	feet	Material Used	Pumped	Poured
2	10	10	concrete grout	<input type="checkbox"/>	<input checked="" type="checkbox"/>
10	12	12	bentonite chips	<input type="checkbox"/>	<input checked="" type="checkbox"/>
				<input type="checkbox"/>	<input type="checkbox"/>
				<input type="checkbox"/>	<input type="checkbox"/>
				<input type="checkbox"/>	<input type="checkbox"/>
				<input type="checkbox"/>	<input type="checkbox"/>

Neat Cement Fluid Weight 94/7 lbs/gal  
Bentonite Grout \_\_\_\_\_ % bentonite  
Date Started 5/28/2014  
Date Completed 5/28/2014

9 DRILLER'S CERTIFICATION

This well was plugged and abandoned under my supervision and the report is true to the best of my knowledge.  
Name Viking Drillers Inc Contractor  
Address 5950 Granite Lake Dr. Contractor  
Granite Bay, CA 95691  
Nevada contractor's license number \_\_\_\_\_  
issued by the State Contractor's Board 0034680  
Nevada driller's license number issued by the \_\_\_\_\_  
Division of Water Resources, the on-site driller DW-2361  
Signed \_\_\_\_\_  
By driller performing actual drilling on site or contractor  
Date 7/31/2014

(Rev. 05-08)

USE ADDITIONAL SHEETS IF NECESSARY

NAD 27  
36.1500744  
- 115.0541964