STATE OF NEVADA
DIVISION OF WATER RESOURCES
WELL DRILLER'S PLUGGING REPORT

OFFICE USE ONLY
Log No. 121952
Permit No.
Basin pun

PRINT OR TYPE ONLY
DO NOT WRITE ON BACK

Please complete this form in its entirety in accordance with NRS 534.170 and NAC 534.340

NOTICE OF INTENT NO. 72249
WELL NAME (If applicable): omw-4d

1 OWNER Veris Gold U.S.A. Inc. Mirinda Jones
MAILING ADDRESS HC 31 Box 78, Elko, NV 89801

ADDRESS AT WELL LOCATION JERRITT CANYON MINE. IN THE MILL AREA
Subdivision Name: County: ELKO

2 LOCATION SE ¼ NW ¼ Sec 33 T 41N N/S R 54 E
PERMIT/WAIVER No. Issued by Water Resources Parcel No.

Latitude 41.408595
Longitude -115.903529
UTM E ☐ NAD 27
N ☒ NAD 83/WGS 8

3 TYPE OF WELL
☐ Domestic ☐ Irrigation ☐ Test
☐ Municipal/Industrial ☒ Monitor ☐ Stock

Is this well being plugged because a replacement well was drilled? YES
If yes, what is replacement well NO? 72248

Is there an existing well log? can't locate
If yes, what is NDWR well log #?

4 EXISTING WELL CONSTRUCTION
Depth Drilled 50 Feet Depth Cased 48 Feet

EXISTING CASING SCHEDULE

Size O.D. (Inches)	Weight/Ft. (Pounds)	Wall Thickness (Inches)	From (Feet)	To (Feet)
2		sch 40	0	48

Existing Perforations:
Type of perforation unsure
Size of perforation

From	38	feet to	48	feet
From		feet to		feet
From		feet to		feet
From		feet to		feet
From		feet to		feet

5 WATER LEVEL
Static water level 46 feet below land surface
Artesian flow G.P.M. P.S.I
Water temperature not taken °F Quality

6 Additional Notes or Comments
Measure the well. It is 2" PVC. The tape went to the depth (48') after a couple times in and out, there was about 3" of (goo) in the bottom of the well.

Plug unknown log
replaced by log 121956

Nad 27
Lt. 40.86556 N
Lo. 115.90261 W

7 WELL PLUGGING PROCEDURE
Was well cleaned out to total depth? ☐ yes ☒ no
If well was not cleaned out to total depth, please explain why:
because the tape measure depth went to the recorded depth.

Was the well contaminated? ☐ yes ☒ no
Was the casing pulled? ☐ yes ☒ no If pulled from: feet to feet
Was the casing over drilled? ☐ yes ☒ no
If casing was left in place, please show where additional perforations were made:

Additional Perforations:
Type of perforater used: None PVC well

From	feet to	feet	Number of perfs per linear foot	
From	feet to	feet	Number of perfs per linear foot	
From	feet to	feet	Number of perfs per linear foot	
From	feet to	feet	Number of perfs per linear foot	
From	feet to	feet	Number of perfs per linear foot	
From	feet to	feet	Number of perfs per linear foot	
From	feet to	feet	Number of perfs per linear foot	
From	feet to	feet	Number of perfs per linear foot	
From	feet to	feet	Number of perfs per linear foot	
From	feet to	feet	Number of perfs per linear foot	
From	feet to	feet	Number of perfs per linear foot	

8 WELL PLUGGING MATERIALS

				Material Used		
From	48	feet to	0 feet	neat cement	☒ Pumped	☐ Poured
From		feet to	feet		☐ Pumped	☐ Poured
From		feet to	feet		☐ Pumped	☐ Poured
From		feet to	feet		☐ Pumped	☐ Poured
From		feet to	feet		☐ Pumped	☐ Poured
From		feet to	feet		☐ Pumped	☐ Poured

Neat Cement Fluid Weight 15.6 lbs/gal
Bentonite Grout % bentonite

Date Started 2/7/2015
Date Completed 2/7/2015

9 DRILLER'S CERTIFICATION
This well was plugged and abandoned under my supervision and the report is true to the best of my knowledge.
Name HAZ-TECH DRILLING INC.
Contractor
Address PO BOX 940 MERIDIAN, ID 83680
Contractor

Nevada contractor's license number issued by the State Contractor's Board 0038018
Nevada driller's license number issued by the Division of Water Resources, the on-site driller M-2188
Signed
By driller performing actual drilling on site or contractor
Date 2/16/2015