

STATE OF NEVADA
DIVISION OF WATER RESOURCES
WELL DRILLER'S PLUGGING REPORT

OFFICE USE ONLY
Log No. 122683
Permit No. 68712T
Basin 1350

PRINT OR TYPE ONLY
DO NOT WRITE ON BACK

Please complete this form in its entirety in
accordance with NRS 534.170 and NAC 534.340

NOTICE OF INTENT NO. 73264
WELL NAME (if applicable): DW-FF1

1 OWNER Round Mountain Gold Corp. ADDRESS AT WELL LOCATION Round Mountain Mine,
MAILING ADDRESS PO Box 480 Round Mountain, NV. 89045 Round Mountain, NV.
Subdivision Name: _____ County: Nye

2 LOCATION NE 1/4 NE 1/4 Sec 30 T 10N N/S R 44 E Latitude 493470 NAD 27
PERMIT/WAIVER No. 68712T R-862 Longitude 4283540 NAD 83/WGS 84
Issued by Water Resources Parcel No. _____

3 TYPE OF WELL Domestic Irrigation Test Monitor Stock
 Municipal/Industrial Is this well being plugged because a replacement well was drilled? No Is there an existing well log? Yes
If yes, what is replacement well NOI? _____ If yes, what is NDWR well log #? 89292

4 EXISTING WELL CONSTRUCTION
Depth Drilled 715 Feet Depth Cased 698 Feet

EXISTING CASING SCHEDULE				
Size O.D. (Inches)	Weight/Ft. (Pounds)	Wall Thickness (Inches)	From (Feet)	To (Feet)
16	42.05	.250	0	60
8.625	33.04	.375	+1.5	698

Existing Perforations:

Type of perforation	Wire Wrapped
Size of perforation	0.08
From 297 feet to	698 feet
From _____ feet to	_____ feet
From _____ feet to	_____ feet
From _____ feet to	_____ feet
From _____ feet to	_____ feet

5 WATER LEVEL
Static water level N/A feet below land surface
Artesian flow N/A G.P.M. N/A P.S.I.
Water temperature N/A °F Quality _____

6 Additional Notes or Comments
Casing collapsed @ 50' from surface.

Materials Used:
125 ea 50lb Holeplug
60 ea Abandonite
35 ea 94lb Cement

Hand 07
35.902 330' W
17.075 0910' W

plugs well log 89292

7 WELL PLUGGING PROCEDURE
Was well cleaned out to total depth? yes no
If well was not cleaned out to total depth, please explain why:
Casing was collapsed @ 50' BGS

Was the well contaminated? yes no
Was the casing pulled? yes no If pulled from: _____ feet to _____ feet
Was the casing over drilled? yes no
If casing was left in place, please show where additional perforations were made:
Additional Perforations:

Type of perforator used:	Holte
From 0 feet to 50 feet	Number of perms per linear foot 24
From _____ feet to _____ feet	Number of perms per linear foot _____
From _____ feet to _____ feet	Number of perms per linear foot _____
From _____ feet to _____ feet	Number of perms per linear foot _____
From _____ feet to _____ feet	Number of perms per linear foot _____
From _____ feet to _____ feet	Number of perms per linear foot _____
From _____ feet to _____ feet	Number of perms per linear foot _____
From _____ feet to _____ feet	Number of perms per linear foot _____
From _____ feet to _____ feet	Number of perms per linear foot _____
From _____ feet to _____ feet	Number of perms per linear foot _____
From _____ feet to _____ feet	Number of perms per linear foot _____
From _____ feet to _____ feet	Number of perms per linear foot _____

8 WELL PLUGGING MATERIALS

Material Used	Neat Cement	3/8 Holeplug	Abandonite	Neat Cement Fluid Weight	Bentonite Grout
From 0 feet to 50 feet	<input checked="" type="checkbox"/> Pumped	<input type="checkbox"/> Pumped	<input type="checkbox"/> Pumped	lbs/gal	% bentonite
From 50 feet to 60 feet	<input type="checkbox"/> Pumped	<input type="checkbox"/> Pumped	<input type="checkbox"/> Pumped		
From 60 feet to 698 feet	<input checked="" type="checkbox"/> Pumped	<input type="checkbox"/> Pumped	<input type="checkbox"/> Pumped		
From _____ feet to _____ feet	<input type="checkbox"/> Pumped	<input type="checkbox"/> Pumped	<input type="checkbox"/> Pumped		
From _____ feet to _____ feet	<input type="checkbox"/> Pumped	<input type="checkbox"/> Pumped	<input type="checkbox"/> Pumped		
From _____ feet to _____ feet	<input type="checkbox"/> Pumped	<input type="checkbox"/> Pumped	<input type="checkbox"/> Pumped		

Date Started 11-Jun-15
Date Completed 13-Jun-15

9 DRILLER'S CERTIFICATION

This well was plugged and abandoned under my supervision and the report is true to the best of my knowledge.

Name Boart Longyear Contractor
Address 2745 California Ave., SLC., UT. 84104 Contractor

Nevada contractor's license number issued by the State Contractor's Board 0021976

Nevada driller's license number issued by the Division of Water Resources, the on-site driller 2462

Signed _____
By driller performing actual drilling on site or contractor

Date 29-Jun-15

2015 JUN -15 PM 1:16
N.V. ENGINEERS & SURVEYORS
BOART LONGYEAR