

**STATE OF NEVADA  
DIVISION OF WATER RESOURCES  
WELL DRILLER'S PLUGGING REPORT**

**OFFICE USE ONLY**

Log No. 122778

Permit No. \_\_\_\_\_

Basin 087

**PRINT OR TYPE ONLY  
DO NOT WRITE ON BACK**

*Please complete this form in its entirety in  
accordance with NRS 534.170 and NAC 534.340*

NOTICE OF INTENT NO. 07174

1 OWNER Atlantic Richfield ADDRESS AT WELL LOCATION \_\_\_\_\_  
 MAILING ADDRESS P.O. Box 6549 6190 S. Virginia Street Reno, NV  
Morago, CA 94570 Subdivision Name: \_\_\_\_\_ County: Washoe

2 LOCATION SW ¼ NW ¼ Sec 31 T 19N N/S R 20 E Latitude 39.469735° UTM E \_\_\_\_\_  NAD 27  
 PERMIT/WAIVER No. 1025-290-16 Longitude -119.785169° N \_\_\_\_\_  NAD 83/WGS 84

Issued by Water Resources Parcel No.

3 TYPE OF WELL Is this well being plugged because a replacement well was drilled? No Is there an existing well log? \_\_\_\_\_

Domestic  Irrigation  Test  No  NAD 27  
 Municipal/Industrial  Monitor  Stock If yes, what is replacement well NOI? \_\_\_\_\_ If yes, what is NDWR well log #? \_\_\_\_\_

4 EXISTING WELL CONSTRUCTION

Depth Drilled \_\_\_\_\_ Feet Depth Cased 34 Feet

EXISTING CASING SCHEDULE

Size O.D. (Inches)	Weight/Ft. (Pounds)	Wall Thickness (Inches)	From (Feet)	To (Feet)
2		SCH 40		

7 WELL PLUGGING PROCEDURE

Was well cleaned out to total depth?  yes  no

If well was not cleaned out to total depth, please explain why: \_\_\_\_\_

Was the well contaminated?  yes  no

Was the casing pulled?  yes  no

Was the casing over drilled?  yes  no

If casing was left in place, please show where additional perforations were made:

Existing Perforations:

Type of perforation	Size of perforation	From	feet to	feet
		From		

Additional Perforations:

Type of perforator used:	From	feet to	feet	Number of perfs per linear foot
	From			

5 WATER LEVEL

Static water level \_\_\_\_\_ feet below land surface

Artesian flow \_\_\_\_\_ G.P.M. \_\_\_\_\_ P.S.I.

Water temperature \_\_\_\_\_ °F Quality \_\_\_\_\_

8 WELL PLUGGING MATERIALS

From	feet to	feet	Material Used	<input type="checkbox"/> Pumped	<input type="checkbox"/> Poured
From	<u>0</u>	<u>34</u>		<input type="checkbox"/>	<input type="checkbox"/>
From				<input type="checkbox"/>	<input type="checkbox"/>
From				<input type="checkbox"/>	<input type="checkbox"/>
From				<input type="checkbox"/>	<input type="checkbox"/>
From				<input type="checkbox"/>	<input type="checkbox"/>
From				<input type="checkbox"/>	<input type="checkbox"/>

6 Additional Notes or Comments

SW-2  
Drillout Top 5' and Mushroom Cap

RECEIVED  
2013 AUG 14 AM 10:54  
STATE ENGINEERS OFFICE

Neat Cement Fluid Weight 20 lbs/gal

Bentonite Grout 5 % bentonite

Date Started 5/14/2013

Date Completed 5/14/2013

9 DRILLER'S CERTIFICATION


This well was plugged and abandoned under my supervision and the report is true to the best of my knowledge.

Name Cascade Drilling, L.P. Contractor

Address 3000 Duluth Street West Sacramento, CA 95691 Contractor

Nevada contractor's license number \_\_\_\_\_ issued by the State Contractor's Board C23-073966

Nevada driller's license number issued by the Division of Water Resources, the on-site driller 1977-M

Signed  By driller performing actual drilling on site or contractor

Date \_\_\_\_\_

(Rev. 05-08)

USE ADDITIONAL SHEETS IF NECESSARY

*Plugging unknown log*