

STATE OF NEVADA
 DIVISION OF WATER RESOURCES
WELL DRILLER'S PLUGGING REPORT

OFFICE USE ONLY
 Log No. 122783
 Permit No. _____
 Basin 104

PRINT OR TYPE ONLY
 DO NOT WRITE ON BACK

Please complete this form in its entirety in
 accordance with NRS 534.170 and NAC 534.340

NOTICE OF INTENT NO. 67173

1 OWNER Atlantic Richfield ADDRESS AT WELL LOCATION _____
 MAILING ADDRESS P.O. Box 6549 1017 North Carson Street Carson City, NV
Morago, CA 94570 Subdivision Name: _____ County: Carson City

2 LOCATION NW ¼ NW ¼ Sec 17 T 15N N/S R 20 E Latitude 39.1700015° UTM E NAD 27
 PERMIT/WAIVER No. 02-161-07 Longitude -119.766743° N NAD 83/WGS 84
Issued by Water Resources Parcel No.

3 TYPE OF WELL Is this well being plugged because a replacement well was drilled? No Is there an existing well log? _____
 Domestic Irrigation Test Municipal/Industrial Monitor Stock
 If yes, what is replacement well NOI? _____ If yes, what is NDWR well log #? _____

4 EXISTING WELL CONSTRUCTION

| | | | | |
|---------------|------|-------------|----|------|
| Depth Drilled | Feet | Depth Cased | 17 | Feet |
|---------------|------|-------------|----|------|

EXISTING CASING SCHEDULE

| Size O.D. (Inches) | Weight/Ft. (Pounds) | Wall Thickness (Inches) | From (Feet) | To (Feet) |
|--------------------|---------------------|-------------------------|-------------|-----------|
| 2 | | SCH 40 | | |
| | | | | |
| | | | | |

7 WELL PLUGGING PROCEDURE

Was well cleaned out to total depth? yes no
 If well was not cleaned out to total depth, please explain why: _____

Was the well contaminated? yes no
 Was the casing pulled? yes no
 Was the casing over drilled? yes no

Existing Perforations:

| Type of perforation | Size of perforation | From | feet to | feet |
|---------------------|---------------------|------|---------|------|
| | | | | |
| | | | | |
| | | | | |
| | | | | |

If casing was left in place, please show where additional perforations were made:

Additional Perforations:

| Type of perforator used: | From | feet to | feet | Number of perfs per linear foot |
|--------------------------|------|---------|------|---------------------------------|
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |

5 WATER LEVEL

Static water level _____ feet below land surface
 Artesian flow _____ G.P.M. _____ P.S.I.
 Water temperature _____ ° F Quality _____

8 WELL PLUGGING MATERIALS

| Material Used | From | feet to | feet | <input type="checkbox"/> Pumped | <input type="checkbox"/> Poured |
|---------------|------|---------|------|---------------------------------|---------------------------------|
| | 0 | 17 | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |

6 Additional Notes or Comments

VW-2
Drillout Top 5' and Mushroom Cap

AUG 14 2013
 10:43 AM
 CIVIL ENGINEERS OFFICE

Neat Cement Fluid Weight 20 lbs/gal
 Bentonite Grout 5 % bentonite
 Date Started 5/6/2013
 Date Completed 5/6/2013

9 DRILLER'S CERTIFICATION

This well was plugged and abandoned under my supervision and the report is true to the best of my knowledge.

Name Cascade Drilling, L.P. Contractor
 Address 3000 Duluth Street West Sacramento, CA 95691 Contractor

Nevada contractor's license number issued by the State Contractor's Board C23-073966
 Nevada driller's license number issued by the Division of Water Resources, the on-site driller 1977-M

Signed [Signature] By driller performing actual drilling on site or contractor
 Date _____

Plugging Unknown log