

**STATE OF NEVADA  
DIVISION OF WATER RESOURCES  
WELL DRILLER'S PLUGGING REPORT**

**OFFICE USE ONLY**  
Log No. 122805  
Permit No. \_\_\_\_\_  
Basin 104

**PRINT OR TYPE ONLY  
DO NOT WRITE ON BACK**

*Please complete this form in its entirety in  
accordance with NRS 534.170 and NAC 534.340*

NOTICE OF INTENT NO. 67173

1 OWNER Atlantic Richfield ADDRESS AT WELL LOCATION \_\_\_\_\_  
MAILING ADDRESS P.O. Box 6549 1017 North Carson Street Carson City, NV  
Morago, CA 94570 Subdivision Name: \_\_\_\_\_ County: Carson City

2 LOCATION NW ¼ NW ¼ Sec 17 T 15N N/S R 20 E Latitude 39° 36' 16.9800" UTM E  NAD 27  
PERMIT/WAIVER No. 02-161-07 Longitude -119.767139° N  NAD 83/WGS 84  
Issued by Water Resources Parcel No.

3 TYPE OF WELL Is this well being plugged because a replacement well was drilled? No Is there an existing well log? \_\_\_\_\_  
 Domestic  Irrigation  Test  Municipal/Industrial  Monitor  Stock If yes, what is replacement well NOI? \_\_\_\_\_ If yes, what is NDWR well log #? \_\_\_\_\_

4 EXISTING WELL CONSTRUCTION

Depth Drilled	Feet	Depth Cased	19	Feet
---------------	------	-------------	----	------

EXISTING CASING SCHEDULE

Size O.D. (Inches)	Weight/Ft. (Pounds)	Wall Thickness (Inches)	From (Feet)	To (Feet)
2		SCH 40		

7 WELL PLUGGING PROCEDURE

Was well cleaned out to total depth?  yes  no

If well was not cleaned out to total depth, please explain why: \_\_\_\_\_

Was the well contaminated?  yes  no

Was the casing pulled?  yes  no

Was the casing over drilled?  yes  no

Existing Perforations:

Type of perforation	Size of perforation	From	feet to	feet

If casing was left in place, please show where additional perforations were made:

Additional Perforations:

Type of perforator used:	From	feet to	feet	Number of perfs per linear foot

5 WATER LEVEL

Static water level \_\_\_\_\_ feet below land surface

Artesian flow \_\_\_\_\_ G.P.M. \_\_\_\_\_ P.S.I.

Water temperature \_\_\_\_\_ °F Quality \_\_\_\_\_

8 WELL PLUGGING MATERIALS

Material Used				Pumped	Poured
From	0	feet to	19 feet	<input type="checkbox"/>	<input type="checkbox"/>
From		feet to	feet	<input type="checkbox"/>	<input type="checkbox"/>
From		feet to	feet	<input type="checkbox"/>	<input type="checkbox"/>
From		feet to	feet	<input type="checkbox"/>	<input type="checkbox"/>
From		feet to	feet	<input type="checkbox"/>	<input type="checkbox"/>
From		feet to	feet	<input type="checkbox"/>	<input type="checkbox"/>

6 Additional Notes or Comments

MW-7

Drillout Top 5' and Mushroom Cap

*(Vertical stamp: AUG 14 10 10 AM 2013 STATE ENGINEERS OF FLORIDA)*

Neat Cement Fluid Weight 20 lbs/gal

Bentonite Grout 5 % bentonite

Date Started 5/7/2013

Date Completed 5/7/2013

9 DRILLER'S CERTIFICATION

This well was plugged and abandoned under my supervision and the report is true to the best of my knowledge.

Name Cascade Drilling, L.P. Contractor

Address 3000 Duluth Street West Sacramento, CA 95691 Contractor

Nevada contractor's license number issued by the State Contractor's Board C23-073966

Nevada driller's license number issued by the Division of Water Resources, the on-site driller 1977-M

Signed [Signature] By driller performing actual drilling on site or contractor

Date \_\_\_\_\_

*Plugging Unknown log*