

**STATE OF NEVADA  
DIVISION OF WATER RESOURCES  
WELL DRILLER'S PLUGGING REPORT**

**OFFICE USE ONLY**  
Log No. 122899  
Permit No. \_\_\_\_\_  
Basin \_\_\_\_\_

**PRINT OR TYPE ONLY  
DO NOT WRITE ON BACK**

*Please complete this form in its entirety in  
accordance with NRS 534.170 and NAC 534.340*

NOTICE OF INTENT NO. 39458  
WELL NAME (if applicable): MW-6

1 OWNER C Lazy H LLC c/o V Hester ADDRESS AT WELL LOCATION 2301 Glendale Blvd  
MAILING ADDRESS 1129 Rice Rd Moapa, NV 89025  
Fallon, NV 89406-5441 Subdivision Name: \_\_\_\_\_ County: Clark

2 LOCATION NE ¼ NE ¼ Sec 2 T 15S N/S R 66 E Latitude 36.66493 UTM E  NAD 27  
PERMIT/WAIVER No. 042-02-501-004 Longitude -114.56902 N  NAD 83/WGS 84

3 TYPE OF WELL  
 Domestic  Irrigation  Test  
 Municipal/Industrial  Monitor  Stock  
Is this well being plugged because a replacement well was drilled? NO  
If yes, what is replacement well NO? \_\_\_\_\_  
Is there an existing well log? \_\_\_\_\_  
If yes, what is NDWR well log #? \_\_\_\_\_

4 EXISTING WELL CONSTRUCTION  
Depth Drilled \_\_\_\_\_ Feet Depth Cased 25 Feet

EXISTING CASING SCHEDULE

Size O.D. (Inches)	Weight/Ft (Pounds)	Wall Thickness (Inches)	From (Feet)	To (Feet)
<u>4</u>	<u>PVC</u>	<u>SCH 40</u>	<u>25</u>	<u>0</u>

Existing Perforations:

Type of perforation	Size of perforation	From	feet to	To	feet
	<u>MACHINE SLOTTED</u>		<u>0.02</u>		
From	<u>25</u>	feet to	<u>5</u>	feet	
From		feet to		feet	
From		feet to		feet	
From		feet to		feet	
From		feet to		feet	

7 WELL PLUGGING PROCEDURE  
Was well cleaned out to total depth?  yes  no  
If well was not cleaned out to total depth, please explain why: \_\_\_\_\_

Was the well contaminated?  yes  no  
Was the casing pulled?  yes  no if pulled from: 25 feet to 0 feet  
Was the casing over drilled?  yes  no  
If casing was left in place, please show where additional perforations were made:  
Additional Perforations:  
Type of perforator used:

From	feet to	feet	Number of perfs per linear foot
From	feet to	feet	Number of perfs per linear foot
From	feet to	feet	Number of perfs per linear foot
From	feet to	feet	Number of perfs per linear foot
From	feet to	feet	Number of perfs per linear foot
From	feet to	feet	Number of perfs per linear foot
From	feet to	feet	Number of perfs per linear foot
From	feet to	feet	Number of perfs per linear foot
From	feet to	feet	Number of perfs per linear foot
From	feet to	feet	Number of perfs per linear foot
From	feet to	feet	Number of perfs per linear foot
From	feet to	feet	Number of perfs per linear foot
From	feet to	feet	Number of perfs per linear foot
From	feet to	feet	Number of perfs per linear foot
From	feet to	feet	Number of perfs per linear foot
From	feet to	feet	Number of perfs per linear foot

5 WATER LEVEL  
Static water level 13 feet below land surface  
Artesian flow \_\_\_\_\_ G.P.M. \_\_\_\_\_ P.S.I.  
Water temperature 74 °F Quality \_\_\_\_\_

6 Additional Notes or Comments  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

8 WELL PLUGGING MATERIALS  
Material Used  
From 25 feet to 0 feet BENTONITE GROUT  Pumped  Poured  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet  Pumped  Poured  
Neat Cement Fluid Weight \_\_\_\_\_ lbs/gal  
Bentonite Grout 28 % bentonite  
Date Started 6/15/2015  
Date Completed 6/15/2015

9 DRILLER'S CERTIFICATION  
This well was plugged and abandoned under my supervision and the report is true to the best of my knowledge.  
Name Eagle Drilling Services LLC  
Address 7150 Placid St Las Vegas, NV 89119  
Nevada contractor's license number \_\_\_\_\_  
issued by the State Contractor's Board 51266  
Nevada driller's license number issued by the Division of Water Resources, the on-site driller 2490-LTD  
Signed \_\_\_\_\_  
Date 6/18/2015

36.6649576  
-114.5681997 NAD  
27

Rev 12-13