

**STATE OF NEVADA
DIVISION OF WATER RESOURCES
WELL DRILLER'S PLUGGING REPORT**

OFFICE USE ONLY

Log No. 122904
 Permit No. _____
 Basin _____

**PRINT OR TYPE ONLY
DO NOT WRITE ON BACK**

*Please complete this form in its entirety in
accordance with NRS 534.170 and NAC 534.340*

NOTICE OF INTENT NO. 39457
 WELL NAME (if applicable): SP-3

1 OWNER C Lazy H LLC c/o V Hester ADDRESS AT WELL LOCATION 2301 Glendale Blvd
 MAILING ADDRESS 1129 Rice Rd. Fallon, NV 89406-5441 Moapa, NV 89025
 Subdivision Name: _____ County: Clark

2 LOCATION NE 1/4 NE 1/4 Sec 2 T 15S N/S R 66 E Latitude 36.66509 UTM E NAD 27
 PERMIT/WAIVER No. 042-02-501-004 Longitude -114.56949 N NAD 83/WGS 84

Issued by Water Resources Parcel No.

3 TYPE OF WELL
 Domestic Irrigation Test
 Municipal/Industrial Monitor Stock

Is this well being plugged because a replacement well was drilled? NO
 If yes, what is replacement well NOI? _____

Is there an existing well log? _____
 If yes, what is NDWR well log #? _____

4 EXISTING WELL CONSTRUCTION

Depth Drilled	Feet	Depth Cased	Feet

EXISTING CASING SCHEDULE

Size O.D. (Inches)	Weight/Ft. (Pounds)	Wall Thickness (Inches)	From (Feet)	To (Feet)
2	PVC	SCH 40	21	0

Existing Perforations:

Type of perforation	Size of perforation	From	feet to	feet
		From	feet to	feet
		From	feet to	feet
		From	feet to	feet
		From	feet to	feet

7 WELL PLUGGING PROCEDURE

Was well cleaned out to total depth? yes no
 If well was not cleaned out to total depth, please explain why: _____

Was the well contaminated? yes no
 Was the casing pulled? yes no If pulled from: _____ feet to _____ feet
 Was the casing over drilled? yes no

If casing was left in place, please show where additional perforations were made:
 Additional Perforations:

Type of perforater used:	From	feet to	feet	Number of perfs per linear foot
	From	feet to	feet	Number of perfs per linear foot
	From	feet to	feet	Number of perfs per linear foot
	From	feet to	feet	Number of perfs per linear foot
	From	feet to	feet	Number of perfs per linear foot
	From	feet to	feet	Number of perfs per linear foot
	From	feet to	feet	Number of perfs per linear foot
	From	feet to	feet	Number of perfs per linear foot
	From	feet to	feet	Number of perfs per linear foot
	From	feet to	feet	Number of perfs per linear foot
	From	feet to	feet	Number of perfs per linear foot

5 WATER LEVEL

Static water level 12 feet below land surface
 Artesian flow _____ G.P.M. _____ P.S.I.
 Water temperature 74 °F Quality _____

6 Additional Notes or Comments

****ATTEMPTED TO PULL CASING.
CASING BROKE OFF AT ONE FOOT
BELOW GROUND SURFACE. KNOCKED OUT
BOTTOM CAP AND GROUTED FROM BOTTOM TO TOP****

DCNR/DWR/SNBO
RECEIVED
JUN 29 2015

8 WELL PLUGGING MATERIALS

Material Used

From	feet to	feet	BENTONITE GROUT	<input checked="" type="checkbox"/> Pumped	<input type="checkbox"/> Poured
From	21	feet to	0	feet	<input type="checkbox"/> Pumped <input type="checkbox"/> Poured
From		feet to		feet	<input type="checkbox"/> Pumped <input type="checkbox"/> Poured
From		feet to		feet	<input type="checkbox"/> Pumped <input type="checkbox"/> Poured
From		feet to		feet	<input type="checkbox"/> Pumped <input type="checkbox"/> Poured
From		feet to		feet	<input type="checkbox"/> Pumped <input type="checkbox"/> Poured
From		feet to		feet	<input type="checkbox"/> Pumped <input type="checkbox"/> Poured

Neat Cement Fluid Weight _____ lbs/gal
 Bentonite Grout 28 % bentonite

Date Started 6/16/2015
 Date Completed 6/16/2015

9 DRILLER'S CERTIFICATION

This well was plugged and abandoned under my supervision and the report is true to the best of my knowledge.

Name Eagle Drilling Services LLC
 Contractor

Address 7150 Placid St Las Vegas, NV 89119
 Contractor

Nevada contractor's license number _____
 issued by the *State Contractor's Board* 51266

Nevada driller's license number issued by the
 Division of Water Resources, the on-site driller 2490-LTD

Signed [Signature]
 By driller performing actual drilling on site or contractor

Date 6/18/2015

36,6651176 NAD
 -114,5686697 27