

STATE OF NEVADA
DIVISION OF WATER RESOURCES
WELL DRILLER'S PLUGGING REPORT

OFFICE USE ONLY
Log No. 122910
Permit No. _____
Basin _____

PRINT OR TYPE ONLY
DO NOT WRITE ON BACK

Please complete this form in its entirety in
accordance with NRS 534.170 and NAC 534.340

NOTICE OF INTENT NO. 37438
WELL NAME (if applicable): #3

1 OWNER CLARK COUNTY ADDRESS AT WELL LOCATION COOPER ST BRIDGE
MAILING ADDRESS 500 S. GRAND CENTRAL PKY CLARK COUNTY, NEV
Subdivision Name: A County: CLARK

2 LOCATION 1/4 Sec 5 E 1/2 Sec 12 T 16 S N 67 E Latitude 36° 33' 16.359" N UTM E 11U 26 31 136 NAD 27
PERMIT/WAIVER No. DA1243 070127960 Longitude 114° 26' 31.136" W NAD 83WGS 84
Issued by Water Resources Parcel No. _____

3 DW TYPE OF WELL Domestic Irrigation Test Municipal/Industrial Monitor Stock
Is this well being plugged because a replacement well was drilled? yes completed Is there an existing well log? yes
If yes, what is replacement well NCI? not a well If yes, what is NDWR well log #? 122150

4 EXISTING WELL CONSTRUCTION

Depth Drilled	Feet	Depth Cased	Feet

EXISTING CASING SCHEDULE				
Size O.D. (Inches)	Weight (Pounds)	Wall Thickness (Inches)	From (Feet)	To (Feet)
<u>1 1/2</u>	<u>34</u>	<u>1/4</u>		

Existing Perforations:
Type of perforation _____
Size of perforation _____
From _____ feet to _____ feet
From _____ feet to _____ feet

5 WATER LEVEL

Static water level _____ feet below land surface
Artesian flow _____ G.P.M. _____ P.S.I.
Water temperature _____ *F _____ Quality _____

6 Additional Notes or Comments

Pumped From Bottom neat Cement

DCNR/DWR/SNBO RECEIVED
JUL 10 2015

7 WELL PLUGGING PROCEDURE

Was well cleaned out to total depth? yes no
If well was not cleaned out to total depth, please explain why: _____

Was the well contaminated? yes no
Was the casing pulled? yes no If pulled from: + 1/2 feet to 30 feet
Was the casing over drilled? yes no

If casing was left in place, please show where additional perforations were made:
Additional Perforations:
Type of perforator used:
From _____ feet to _____ feet Number of perms per linear foot _____
From _____ feet to _____ feet Number of perms per linear foot _____
From _____ feet to _____ feet Number of perms per linear foot _____
From _____ feet to _____ feet Number of perms per linear foot _____
From _____ feet to _____ feet Number of perms per linear foot _____
From _____ feet to _____ feet Number of perms per linear foot _____
From _____ feet to _____ feet Number of perms per linear foot _____
From _____ feet to _____ feet Number of perms per linear foot _____
From _____ feet to _____ feet Number of perms per linear foot _____
From _____ feet to _____ feet Number of perms per linear foot _____
From _____ feet to _____ feet Number of perms per linear foot _____
From _____ feet to _____ feet Number of perms per linear foot _____
From _____ feet to _____ feet Number of perms per linear foot _____

8 WELL PLUGGING MATERIALS

Material Used
From _____ feet to _____ feet Pumped Poured
Neat Cement Fluid Weight new cement lbs/gal 17.28
Bentonite Grout _____ % bentonite

Date Started May 30 2015
Date Completed May 30 2015

9 DRILLER'S CERTIFICATION

This well was plugged and abandoned under my supervision and the report is true to the best of my knowledge.
Name Melvin Dewatering Contractor
Address 10162 E Coldwater Rd Contractor
Davidson Mi 48423
Nevada contractor's license number _____
issued by the State Contractor's Board BC074472
Nevada driller's license number issued by the _____
Division of Water Resources, the on-site driller 2325
Signed [Signature] By driller performing actual drilling on site or contractor
Date June 26, 2015