

STATE OF NEVADA  
DIVISION OF WATER RESOURCES  
WELL DRILLER'S PLUGGING REPORT

OFFICE USE ONLY  
Log No. 122950  
Permit No. \_\_\_\_\_  
Basin \_\_\_\_\_

PRINT OR TYPE ONLY  
DO NOT WRITE ON BACK

Please complete this form in its entirety in  
accordance with NRS 534.170 and NAC 534.340

NOTICE OF INTENT NO. 39431  
WELL NAME (if applicable): #39

1 OWNER CLARK County  
MAILING ADDRESS 500 S. Grand Central PKY

ADDRESS AT WELL LOCATION COOPER ST BRIDGE  
COVINGTON, NEV

2 LOCATION NW 1/4 SE 1/4 Sec 12 T 16 S N 36 R 67 E  
PERMIT/WAIVER No. NDW 13443

Subdivision Name: A County: CLARK  
Latitude 36° 33' 26.81" N  NAD 27  
Longitude 114° 26' 28.68" W  NAD 83/WGS 8

3 TYPE OF WELL  
 Domestic  Irrigation  Test  
 Municipal/Industrial  Monitor  Stock

Is this well being plugged because a replacement well was drilled? Yes  COMPLETED  
Is there an existing well log? Yes   
If yes, what is replacement well NOI? NO longer  
If yes, what is NDWR well log #? 122161

4 EXISTING WELL CONSTRUCTION  
Depth Drilled \_\_\_\_\_ Feet Depth Cased \_\_\_\_\_ Feet

7 WELL PLUGGING PROCEDURE  
Was well cleaned out to total depth?  yes  no

EXISTING CASING SCHEDULE				
Size O.D. (Inches)	Weight/Ft. (Pounds)	Wall Thickness (Inches)	From (Feet)	To (Feet)
<u>12.75</u>		<u>1/4</u>		

If well was not cleaned out to total depth, please explain why: \_\_\_\_\_  
Was the well contaminated?  yes  no  
Was the casing pulled?  yes  no If pulled from: +1 1/2 feet to 30 feet  
Was the casing over drilled?  yes  no

Existing Perforations:

From	Type of perforation	Size of perforation	feet to	feet
From				

Additional Perforations:

From	Type of perforator used:	feet to	feet	Number of perfs per linear foot
From				

5 WATER LEVEL  
Static water level \_\_\_\_\_ feet below land surface  
Artesian flow \_\_\_\_\_ G.P.M. \_\_\_\_\_ P.S.I.  
Water temperature \_\_\_\_\_ °F Quality \_\_\_\_\_

6 Additional Notes or Comments

pumped from  
bottom neat  
Cement

8 WELL PLUGGING MATERIALS

From	feet to	feet	Material Used	<input checked="" type="checkbox"/> Pumped	<input type="checkbox"/> Poured
From				<input type="checkbox"/> Pumped	<input type="checkbox"/> Poured
From				<input type="checkbox"/> Pumped	<input type="checkbox"/> Poured
From				<input type="checkbox"/> Pumped	<input type="checkbox"/> Poured
From				<input type="checkbox"/> Pumped	<input type="checkbox"/> Poured
From				<input type="checkbox"/> Pumped	<input type="checkbox"/> Poured

Neat Cement Fluid Weight neat cement lbs/gal 12.25  
Bentonite Grout \_\_\_\_\_ % bentonite

Date Started May 6 2015  
Date Completed May 6 2015

DCNR/DWR/SNRC  
RECEIVED  
JUL 30 2015

9 DRILLER'S CERTIFICATION

This well was plugged and abandoned under my supervision and the report is true to the best of my knowledge.  
Name Merlino Dewatering Contractor  
Address 10162 E Coldwater Rd Contractor  
Davidson Mi 48423  
Nevada contractor's license number \_\_\_\_\_  
issued by the State Contractor's Board 0026472  
Nevada driller's license number issued by the \_\_\_\_\_  
Division of Water Resources, the on-site driller 2325  
Signed Highland Driller performing actual drilling on site or contractor  
Date June 26 2015

36.5574472  
- 114.443911  
NAD  
27