

**STATE OF NEVADA  
DIVISION OF WATER RESOURCES  
WELL DRILLER'S PLUGGING REPORT**

OFFICE USE ONLY  
Log No. 122955  
Permit No. \_\_\_\_\_  
Basin \_\_\_\_\_

PRINT OR TYPE ONLY  
DO NOT WRITE ON BACK

Please complete this form in its entirety in  
accordance with NRS 534.170 and NAC 534.340

NOTICE OF INTENT NO. 87431  
WELL NAME (if applicable): #445

1 OWNER CLARK COUNTY  
MAILING ADDRESS 500 S. Grand Central PKY

ADDRESS AT WELL LOCATION COOPER ST BRIDGE  
Subdivision Name: A County: CLARK

2 LOCATION 1/4 SE 1/4 Sec 12 T 16 S N 3 R 67 E  
PERMIT/WAIVER No. DAW 1343 070 12696 004  
Issued by Water Resources Parcel No.

Latitude 36° 33' 24.60" N Longitude 114° 26' 39.01" W  
 NAD 27  
 NAD 83/WGS 84

3  Domestic  Irrigation  Test  
 Municipal/Industrial  Monitor  Stock

Is this well being plugged because a replacement well was drilled? yes completed  
If yes, what is replacement well NCI? not known  
Is there an existing well log? yes  
If yes, what is NDWR well log #? 122158

**4 EXISTING WELL CONSTRUCTION**

Depth Drilled	Feet	Depth Cased	Feet

**EXISTING CASING SCHEDULE**

Size O.D. (Inches)	Weight/Ft. (Pounds)	Wall Thickness (Inches)	From (Feet)	To (Feet)
<u>12 1/4"</u>		<u>1/2"</u>		

**5 WATER LEVEL**  
Static water level \_\_\_\_\_ feet below land surface  
Artesian flow \_\_\_\_\_ G.P.M. \_\_\_\_\_ P.S.I.  
Water temperature \_\_\_\_\_ °F Quality \_\_\_\_\_

**6 Additional Notes or Comments**

Well washed out in flood  
R 1691

**7 WELL PLUGGING PROCEDURE**

Was well cleaned out to total depth?  yes  no  
If well was not cleaned out to total depth, please explain why: \_\_\_\_\_  
Was the well contaminated?  yes  no  
Was the casing pulled?  yes  no If pulled from: \_\_\_\_\_ feet to \_\_\_\_\_ feet  
Was the casing over drilled?  yes  no  
If casing was left in place, please show where additional perforations were made:  
Additional Perforations:  
Type of perforator used:  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perms per linear foot \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perms per linear foot \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perms per linear foot \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perms per linear foot \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perms per linear foot \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perms per linear foot \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perms per linear foot \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perms per linear foot \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perms per linear foot \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perms per linear foot \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perms per linear foot \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perms per linear foot \_\_\_\_\_

**8 WELL PLUGGING MATERIALS**

**Material Used**  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet  Pumped  Poured  
Neat Cement Fluid Weight 12.25 lbs/gal  
Bentonite Grout \_\_\_\_\_ % bentonite  
Date Started \_\_\_\_\_  
Date Completed \_\_\_\_\_

**9 DRILLER'S CERTIFICATION**

This well was plugged and abandoned under my supervision and the report is true to the best of my knowledge.  
Name Mervino Dewatering Contractor  
Address 10162 E. Coldwater Rd Contractor  
Davidson Mi 48423  
Nevada contractor's license number \_\_\_\_\_  
issued by the State Contractor's Board 0024472  
Nevada driller's license number issued by the \_\_\_\_\_  
Division of Water Resources, the on-site driller 2325  
Signed [Signature] By driller performing actual drilling on site of contractor  
Date June 26 2015

DCNR/DWR/SNBO  
RECEIVED  
JUL 10 2015

36.55795  
-114.4446945 NAD 27