STATE OF NEVADA
DIVISION OF WATER RESOURCES
# WELL DRILLER'S PLUGGING REPORT

OFFICE USE ONLY
Log No. 123340
Permit No.
Basin

PRINT OR TYPE ONLY
DO NOT WRITE ON BACK

*Please complete this form in its entirety in accordance with NRS 534.170 and NAC 534.340*

NOTICE OF INTENT NO 39478
WELL NAME (*if applicable*): DBMW-14

1 OWNER Greystone Nevada LLC
MAILING ADDRESS 2490 Paseo Verde Pkwy #120
Henderson, NV 89074

ADDRESS AT WELL LOCATION 444 Middlestone Ave.
Henderson, NV 89011
*Subdivision Name* *County* Clark

2 LOCATION NW ¼ NE ¼ Sec 5 T 22S N/S R 63 E
PERMIT/WAIVER No 179-05-515-021
*Issued by Water Resources* *Parcel No.*

Latitude 36.070755
Longitude -114.964692
UTM E
N
☐ NAD 27
☒ NAD 83/WGS 8

3 TYPE OF WELL
☐ Domestic ☐ Irrigation ☐ Test
☐ Municipal/Industrial ☒ Monitor ☐ Stock

Is this well being plugged because a replacement well was drilled? no
If yes, what is replacement well NOI?

Is there an existing well log?
If yes, what is NDWR well log #?

4 *EXISTING WELL CONSTRUCTION*
Depth Drilled Feet Depth Cased 68 Feet

*EXISTING CASING SCHEDULE*

| Size O.D. (Inches) | Weight/Ft. (Pounds) | Wall Thickness (Inches) | From (Feet) | To (Feet) |
|---|---|---|---|---|
| 4 | PVC | SCH 40 | 0 | 68 |
| | | | | |
| | | | | |
| | | | | |

*Existing Perforations*
Type of perforation MACHINE SLOTTED
Size of perforation 0.02

| | | | |
|---|---|---|---|
| From | feet to | | feet |
| From | feet to | | feet |
| From | feet to | | feet |
| From | feet to | | feet |
| From | feet to | | feet |

5 *WATER LEVEL*
*Static water level* 43 feet below land surface
Artesian flow G.P.M. P.S.I
Water temperature 76 °F Quality

6 Additional Notes or Comments

**CASING BROKE OFF AT 10 FT BELOW GROUND SURFACE. KNOCKED OUT BOTTOM. AND GROUTED FROM BOTTOM TO TOP WITH TREMIE**

DCNR/DWR/SNBC
RECEIVED
SEP 11 2015

7 WELL PLUGGING PROCEDURE
Was well cleaned out to total depth? ☒ yes ☐ no
If well was not cleaned out to total depth, please explain why:

Was the well contaminated? ☐ yes ☒ no
Was the casing pulled? ☒ yes ☐ no If pulled from: 10 feet to 0 feet
Was the casing over drilled? ☐ yes ☒ no
If casing was left in place, please show where additional perforations were made:

*Additional Perforations*
Type of perforater used:

| | | | | |
|---|---|---|---|---|
| From | feet to | | feet | Number of perfs per linear foot |
| From | feet to | | feet | Number of perfs per linear foot |
| From | feet to | | feet | Number of perfs per linear foot |
| From | feet to | | feet | Number of perfs per linear foot |
| From | feet to | | feet | Number of perfs per linear foot |
| From | feet to | | feet | Number of perfs per linear foot |
| From | feet to | | feet | Number of perfs per linear foot |
| From | feet to | | feet | Number of perfs per linear foot |
| From | feet to | | feet | Number of perfs per linear foot |
| From | feet to | | feet | Number of perfs per linear foot |
| From | feet to | | feet | Number of perfs per linear foot |

8 WELL PLUGGING MATERIALS

| | | | | Material Used | | |
|---|---|---|---|---|---|---|
| From | 68 | feet to | 0 feet | BENTONITE GROUT | ☒ Pumped | ☐ Poured |
| From | | feet to | feet | | ☐ Pumped | ☐ Poured |
| From | | feet to | feet | | ☐ Pumped | ☐ Poured |
| From | | feet to | feet | | ☐ Pumped | ☐ Poured |
| From | | feet to | feet | | ☐ Pumped | ☐ Poured |
| From | | feet to | feet | | ☐ Pumped | ☐ Poured |

Neat Cement Fluid Weight lbs/gal
Bentonite Grout 26 % bentonite

Date Started 9/4/2015
Date Completed 9/4/2015

9 DRILLER'S CERTIFICATION
This well was plugged and abandoned under my supervision and the report is true to the best of my knowledge.

Name EAGLE DRILLING SERVICES, LLC.
Contractor
Address 7150 PLACID ST LAS VEGAS, NV 89119
Contractor

Nevada contractor's license number issued by the *State Contractor's Board* 51266
Nevada driller's license number issued by the Division of Water Resources, the *on-site driller* 2490-LTD
Signed
By driller performing actual drilling on site or contractor
Date 9/8/2015

(Rev 12-13)

USE ADDITIONAL SHEETS IF NECESSARY pg. of pg.

36.0707789
-114.9638659
NAD 27