

STATE OF NEVADA
DIVISION OF WATER RESOURCES
WELL DRILLER'S PLUGGING REPORT

OFFICE USE ONLY
Log No. 123348
Permit No. _____
Basin _____

PRINT OR TYPE ONLY
DO NOT WRITE ON BACK

Please complete this form in its entirety in
accordance with NRS 534.170 and NAC 534.340

NOTICE OF INTENT NO. 39479
WELL NAME (if applicable): DM-8

1 OWNER Greystone Nevada LLC ADDRESS AT WELL LOCATION 429 Middlestone Ave.
MAILING ADDRESS 2490 Paseo Verde Pkwy #120 Henderson, NV
Henderson, NV 89074 Subdivision Name: _____ County: Clark

2 LOCATION NW ¼ NE ¼ Sec 5 T 22S N/S 63 E Latitude 36.070312 UTM E NAD 27
PERMIT/WAIVER No. 179-05-515-032 Longitude -114.965362 N NAD 83/WGS 84
Issued by Water Resources Parcel No. _____

3 TYPE OF WELL Is this well being plugged because a replacement well was drilled? no Is there an existing well log? _____
 Domestic Irrigation Test Municipal/Industrial Monitor Stock If yes, what is NDWR well log #? _____
If yes, what is replacement well NOI? _____

4 EXISTING WELL CONSTRUCTION
Depth Drilled _____ Feet Depth Cased 66 Feet

7 WELL PLUGGING PROCEDURE
Was well cleaned out to total depth? yes no
If well was not cleaned out to total depth, please explain why: _____

EXISTING CASING SCHEDULE

Size O.D. (Inches)	Weight/Ft. (Pounds)	Wall Thickness (Inches)	From (Feet)	To (Feet)
<u>4</u>	<u>PVC</u>	<u>SCH 40</u>	<u>0</u>	<u>66</u>

Was the well contaminated? yes no
Was the casing pulled? yes no If pulled from: 8 feet to 0 feet
Was the casing over drilled? yes no

Existing Perforations:
Type of perforation MACHINE SLOTTED
Size of perforation 0.02
From _____ feet to _____ feet
From _____ feet to _____ feet

If casing was left in place, please show where additional perforations were made:
Additional Perforations:
Type of perforator used:
From _____ feet to _____ feet Number of perfs per linear foot _____
From _____ feet to _____ feet Number of perfs per linear foot _____
From _____ feet to _____ feet Number of perfs per linear foot _____
From _____ feet to _____ feet Number of perfs per linear foot _____
From _____ feet to _____ feet Number of perfs per linear foot _____
From _____ feet to _____ feet Number of perfs per linear foot _____
From _____ feet to _____ feet Number of perfs per linear foot _____
From _____ feet to _____ feet Number of perfs per linear foot _____
From _____ feet to _____ feet Number of perfs per linear foot _____
From _____ feet to _____ feet Number of perfs per linear foot _____
From _____ feet to _____ feet Number of perfs per linear foot _____
From _____ feet to _____ feet Number of perfs per linear foot _____

5 WATER LEVEL
Static water level 50 feet below land surface
Artesian flow _____ G.P.M. _____ P.S.I.
Water temperature 76 °F Quality _____

6 Additional Notes or Comments

8 WELL PLUGGING MATERIALS

****CASING BROKE OFF AT 8 FT BELOW GROUND SURFACE. KNOCKED OUT BOTTOM. AND GROUTED FROM BOTTOM TO TOP WITH TREMIE****

Material Used
From 66 feet to 0 feet BENTONITE GROUT Pumped Poured
From _____ feet to _____ feet Pumped Poured

Neat Cement Fluid Weight _____ lbs/gal
Bentonite Grout 28 % bentonite

Date Started 9/4/2015
Date Completed 9/4/2015

RECEIVED
SEP 17 2015

9 DRILLER'S CERTIFICATION
This well was plugged and abandoned under my supervision and the report is true to the best of my knowledge.

Name EAGLE DRILLING SERVICES, LLC. Contractor
Address 7150 PLACID ST LAS VEGAS, NV 89119 Contractor

Nevada contractor's license number issued by the State Contractor's Board 51266

Nevada driller's license number issued by the Division of Water Resources, the on-site driller 2490-LTD

Signed [Signature] By driller performing actual drilling on site as contractor
Date 9/8/2015

36.0703359 NAD
- 114.9645359 27