STATE OF NEVADA
DIVISION OF WATER RESOURCES
WELL DRILLER'S PLUGGING REPORT

OFFICE USE ONLY
Log No. 123349
Permit No.
Basin

PRINT OR TYPE ONLY
DO NOT WRITE ON BACK

Please complete this form in its entirety in accordance with NRS 534.170 and NAC 534.340

NOTICE OF INTENT NO. 39480
WELL NAME *(If applicable)*: DBMW-13

1 OWNER Greystone Nevada LLC
MAILING ADDRESS 2490 Paseo Verde Pkwy #120
Henderson, NV 89074

ADDRESS AT WELL LOCATION 416 Middlestone Ave.
Henderson, NV 89011
Subdivision Name: *County:* Clark

2 LOCATION NW ¼ NE ¼ Sec 5 T 22S N/S R 63 E
PERMIT/WAIVER No. 179-05-515-014
Issued by Water Resources *Parcel No.*

Latitude 36.070770
Longitude -114.966081
UTM E
N
☐ NAD 27
☒ NAD 83/WGS 8

3 TYPE OF WELL
☐ Domestic ☐ Irrigation ☐ Test
☐ Municipal/Industrial ☒ Monitor ☐ Stock

Is this well being plugged because a replacement well was drilled? no
If yes, what is replacement well NOI?

Is there an existing well log?
If yes, what is NDWR well log #?

4 *EXISTING WELL CONSTRUCTION*
Depth Drilled Feet Depth Cased 62 Feet

EXISTING CASING SCHEDULE

Size O.D. (Inches)	Weight/Ft. (Pounds)	Wall Thickness (Inches)	From (Feet)	To (Feet)
4	PVC	SCH 40	0	62

Existing Perforations:
Type of perforation MACHINE SLOTTED
Size of perforation 0.02

From feet to feet
From feet to feet
From feet to feet
From feet to feet
From feet to feet

5 *WATER LEVEL*
Static water level 56 feet below land surface
Artesian flow G.P.M. P.S.I
Water temperature 75 °F Quality

6 Additional Notes or Comments

CASING BROKE OFF AT 7 FT BELOW GROUND SURFACE. KNOCKED OUT BOTTOM. AND GROUTED FROM BOTTOM TO TOP WITH TREMIE

DCNR/DWR/SNBC
RECEIVED
SEP 1 1 2015

7 WELL PLUGGING PROCEDURE
Was well cleaned out to total depth? ☒ yes ☐ no
If well was not cleaned out to total depth, please explain why:

Was the well contaminated? ☐ yes ☒ no
Was the casing pulled? ☒ yes ☐ no If pulled from: 7 feet to 0 feet
Was the casing over drilled? ☐ yes ☒ no
If casing was left in place, please show where additional perforations were made:

Additional Perforations:
Type of perforater used:

From feet to feet Number of perfs per linear foot
From feet to feet Number of perfs per linear foot
From feet to feet Number of perfs per linear foot
From feet to feet Number of perfs per linear foot
From feet to feet Number of perfs per linear foot
From feet to feet Number of perfs per linear foot
From feet to feet Number of perfs per linear foot
From feet to feet Number of perfs per linear foot
From feet to feet Number of perfs per linear foot
From feet to feet Number of perfs per linear foot
From feet to feet Number of perfs per linear foot

8 WELL PLUGGING MATERIALS

			Material Used		
From 62	feet to 0	feet	BENTONITE GROUT	☒ Pumped	☐ Poured
From	feet to	feet		☐ Pumped	☐ Poured
From	feet to	feet		☐ Pumped	☐ Poured
From	feet to	feet		☐ Pumped	☐ Poured
From	feet to	feet		☐ Pumped	☐ Poured
From	feet to	feet		☐ Pumped	☐ Poured

Neat Cement Fluid Weight lbs/gal
Bentonite Grout 28 % bentonite

Date Started 9/4/2015
Date Completed 9/4/2015

9 DRILLER'S CERTIFICATION
This well was plugged and abandoned under my supervision and the report is true to the best of my knowledge.

Name EAGLE DRILLING SERVICES, LLC.
Contractor

Address 7150 PLACID ST LAS VEGAS, NV 89119
Contractor

Nevada contractor's license number issued by the *State Contractor's Board* 51266
Nevada driller's license number issued by the Division of Water Resources, the *on-site driller* 2490-LTD

Signed
By driller performing actual drilling on site or contractor

Date 9/8/2015

(Rev. 12-13)

USE ADDITIONAL SHEETS IF NECESSARY pg. of pg.

36.0707939 NAD
-114.9652548 27