

STATE OF NEVADA  
DIVISION OF WATER RESOURCES  
WELL DRILLER'S PLUGGING REPORT

OFFICE USE ONLY  
Log No. 123364  
Permit No. \_\_\_\_\_  
Basin \_\_\_\_\_

PRINT OR TYPE ONLY  
DO NOT WRITE ON BACK

Please complete this form in its entirety in  
accordance with NRS 534.170 and NAC 534.340

1 OWNER T & P Notch ADDRESS AT WELL LOCATION 2735 Candalaria NOTICE OF INTENT NO. 38285  
MAILING ADDRESS 9240 EL Camino Rd. Henderson NV Subdivision Name \_\_\_\_\_ County \_\_\_\_\_  
Las Vegas, NV 89139

2 LOCATION NE 1/4 SE 1/4 Sec 24 T 22 N S R 61 E Latitude 36.019145 UTM E \_\_\_\_\_  NAD 27  
PERMIT/WAIVER No. 177-24-703-201 Longitude 115.104311 N  NAD 83/WGS 84  
Issued by Water Resources Parcel No. 177 24711021

3 TYPE OF WELL  
 Domestic  Irrigation  Test  
 Municipal/Industrial  Monitor  Stock  
Is this well being plugged because a replacement well was drilled? NO  
If yes, what is replacement well NOI? \_\_\_\_\_  
Is there an existing well log? YES  
If yes, what is NDWR well log #? 57494

4 EXISTING WELL CONSTRUCTION  
Depth Drilled N/A Feet Depth Cased \_\_\_\_\_ Feet  
EXISTING CASING SCHEDULE  
Size O.D. (Inches) Weight/Ft. (Pounds) Wall Thickness (Inches) From (Feet) To (Feet)  
8 5/8 \_\_\_\_\_ 156 \_\_\_\_\_  
Not Much Casing Left In Hole

7 WELL PLUGGING PROCEDURE  
Was well cleaned out to total depth?  yes  no  
If well was not cleaned out to total depth, please explain why:  
Pump And Wall Seal Was In Well, After Pulling Pump We Ran To Bottom of Hole 319ft Clean  
Was the well contaminated?  yes  no  
Was the casing pulled?  yes  no  
Was the casing over drilled?  yes  no  
If casing was left in place, please show where additional perforations were made:  
Additional Perforations:  
Type of perforater used: Holte

Existing Perforations:

Type of perforation	Size of perforation	From	feet to	feet
From			feet to	feet
From			feet to	feet
From			feet to	feet
From			feet to	feet
From			feet to	feet

Additional Perforations:

Type of perforater used:	From	feet to	feet	Number of perfs per linear foot
<u>Holte</u>	<u>0.319</u>	<u>Surface</u>	<u>feet</u>	<u>4 Rows 16</u>

5 WATER LEVEL  
Static water level \_\_\_\_\_ feet below land surface  
Artesian flow \_\_\_\_\_ G.P.M. \_\_\_\_\_ P.S.I.  
Water temperature \_\_\_\_\_ °F Quality \_\_\_\_\_

8 WELL PLUGGING MATERIALS  
Material Used  
From 319 feet to Surface feet 12 Sack  Pumped  Poured  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet  Pumped  Poured

6 Additional Notes or Comments  
4 Rows At 4 Cuts Per Ft.

Neat Cement Fluid Weight \_\_\_\_\_ lbs/gal  
Bentonite Grout \_\_\_\_\_ % bentonite  
Date Started 5-14-15  
Date Completed 5-14-15

DCNR/DWR/SNBO  
RECEIVED  
MAY 26 2015

9 DRILLER'S CERTIFICATION  
This well was plugged and abandoned under my supervision and the report is true to the best of my knowledge  
Name Redding Drilling Contractor  
Address 9555 Las Vegas Blvd. So. Las Vegas, NV 89123 Contractor  
Nevada contractor's license number issued by the State Contractor's Board 38155  
Nevada driller's license number issued by the Division of Water Resources, the on-site driller 2325  
Signed \_\_\_\_\_  
By driller performing actual drilling on-site or contractor  
Date May 14-15