STATE OF NEVADA
DIVISION OF WATER RESOURCES
WELL DRILLER'S PLUGGING REPORT

OFFICE USE ONLY
Log No. 123402
Permit No.
Basin

PRINT OR TYPE ONLY
DO NOT WRITE ON BACK

Please complete this form in its entirety in accordance with NRS 534.170 and NAC 534.340

NOTICE OF INTENT NO. 39454
WELL NAME (If applicable): MW-11

1 OWNER Moapa Town Center LLC
MAILING ADDRESS 2725 Sunrise Day Ct.
Las Vegas, Nv 89142

ADDRESS AT WELL LOCATION Moapa
(East of 2300 Glendale Blvd.)
Subdivision Name: County: Clark

2 LOCATION NE ¼ NE ¼ Sec 2 T 15S N/S R 66 E/W
PERMIT/WAIVER No. 042-02-501-016
Issued by Water Resources Parcel No.

Latitude 36.66582
Longitude -114.56970
UTM E
N
☐ NAD 27
☒ NAD 83/WGS 8

3 TYPE OF WELL
☐ Domestic ☐ Irrigation ☐ Test
☐ Municipal/Industrial ☒ Monitor ☐ Stock

Is this well being plugged because a replacement well was drilled? NO
If yes, what is replacement well NOI?

Is there an existing well log? YES
If yes, what is NDWR well log #? 118830

4 EXISTING WELL CONSTRUCTION
Depth Drilled Feet Depth Cased Feet

EXISTING CASING SCHEDULE

Size O.D. (Inches)	Weight/Ft. (Pounds)	Wall Thickness (Inches)	From (Feet)	To (Feet)
4	PVC	SCH 40	20	0

Existing Perforations:
Type of perforation MACHINE SLOTTED
Size of perforation 0.02

From	20	feet to	5 feet
From		feet to	feet
From		feet to	feet
From		feet to	feet
From		feet to	feet

5 WATER LEVEL
Static water level 10 feet below land surface
Artesian flow G.P.M. P.S.I
Water temperature 74 °F Quality

6 Additional Notes or Comments

DCNR/DWR/SNBO
RECEIVED
JUN 29 2015

7 WELL PLUGGING PROCEDURE
Was well cleaned out to total depth? ☒ yes ☐ no
If well was not cleaned out to total depth, please explain why:

Was the well contaminated? ☒ yes ☐ no
Was the casing pulled? ☒ yes ☐ no If pulled from: 20 feet to 0 feet
Was the casing over drilled? ☐ yes ☒ no
If casing was left in place, please show where additional perforations were made:

Additional Perforations
Type of perforater used:

From	feet to	feet	Number of perfs per linear foot		
From	feet to	feet	Number of perfs per linear foot		
From	feet to	feet	Number of perfs per linear foot		
From	feet to	feet	Number of perfs per linear foot		
From	feet to	feet	Number of perfs per linear foot		
From	feet to	feet	Number of perfs per linear foot		
From	feet to	feet	Number of perfs per linear foot		
From	feet to	feet	Number of perfs per linear foot		
From	feet to	feet	Number of perfs per linear foot		
From	feet to	feet	Number of perfs per linear foot		
From	feet to	feet	Number of perfs per linear foot		
From	feet to	feet	Number of perfs per linear foot		

8 WELL PLUGGING MATERIALS

				Material Used		
From	20	feet to	0 feet	BENTONITE GROUT	☒ Pumped	☐ Poured
From		feet to	feet		☐ Pumped	☐ Poured
From		feet to	feet		☐ Pumped	☐ Poured
From		feet to	feet		☐ Pumped	☐ Poured
From		feet to	feet		☐ Pumped	☐ Poured
From		feet to	feet		☐ Pumped	☐ Poured

Neat Cement Fluid Weight lbs/gal
Bentonite Grout 28 % bentonite

Date Started 6/17/2015
Date Completed 6/17/2015

9 DRILLER'S CERTIFICATION
This well was plugged and abandoned under my supervision and the report is true to the best of my knowledge.

Name Eagle Drilling Services LLC
Contractor

Address 7150 Placid St Las Vegas, NV 89119
Contractor

Nevada contractor's license number issued by the *State Contractor's Board* 51266
Nevada driller's license number issued by the Division of Water Resources, the *on-site driller* 2490-LTD

Signed
By driller performing actual drilling on site or contractor

Date 6/18/2015

(Rev. 12-03)

USE ADDITIONAL SHEETS IF NECESSARY pg. of pg.

36.66588477
-114.5688797
NAD 27