STATE OF NEVADA
DIVISION OF WATER RESOURCES
WELL DRILLER'S PLUGGING REPORT

OFFICE USE ONLY
Log No. 123458
Permit No.
Basin

PRINT OR TYPE ONLY
DO NOT WRITE ON BACK

Please complete this form in its entirety in accordance with NRS 534.170 and NAC 534.340

NOTICE OF INTENT NO
WELL NAME *(If applicable)*

1 OWNER County of Clark (Aviation)
MAILING ADDRESS PO Box 11005
Las Vegas, NV 89111-1005

ADDRESS AT WELL LOCATION Enterprise
SEC of Blue Diamond Rd and Hinson St, Las Vegas NV 89139
Subdivision Name *County* Clark

2 LOCATION SE ¼ NE ¼ Sec 18 T 22S N/S R 61 E
PERMIT/WAIVER No
Issued by Water Resources
177-18-602-022
Parcel No

Latitude 36.036804
Longitude -115.193056
UTM E
N
☐ NAD 27
☒ NAD 83/WGS 6

3 TYPE OF WELL
☐ Domestic ☐ Irrigation ☐ Test
☐ Municipal/Industrial ☐ Monitor ☐ Stock

Is this well being plugged because a replacement well was drilled? No
If yes, what is replacement well NO?

Is there an existing well log?
If yes, what is NDWR well log #?

4 *EXISTING WELL CONSTRUCTION*
Depth Drilled 135 Feet Depth Cased 21 Feet

EXISTING CASING SCHEDULE

Size O.D. (Inches)	Weight/Ft. (Pounds)	Wall Thickness (Inches)	From (Feet)	To (Feet)
8 5/8			0	21

Existing Perforations
Type of perforation None
Size of perforation

From feet to feet
From feet to feet
From feet to feet
From feet to feet
From feet to feet

5 *WATER LEVEL*
Static water level feet below land surface
Artesian flow G.P.M. P.S.I
Water temperature °F Quality

6 Additional Notes or Comments

After investigation it was determined that this was a Borehole with 8" x 21' steel casing. It was an open hole from the bottom of the casing to 135'. No evidence of water or pump and draw pipe. Tremmied 3 yards of neat cement from bottom to surface. Casing was not pulled.

DCNR/DWR/SNRO
RECEIVED
SEP 30 2015

7 WELL PLUGGING PROCEDURE
Was well cleaned out to total depth? ☒ yes ☐ no
If well was not cleaned out to total depth, please explain why:

Was the well contaminated? ☐ yes ☒ no
Was the casing pulled? ☐ yes ☒ no If pulled from: feet to feet
Was the casing over drilled? ☐ yes ☒ no
If casing was left in place, please show where additional perforations were made:
Additional Perforations
Type of perforater used:

From feet to feet Number of perfs per linear foot
From feet to feet Number of perfs per linear foot
From feet to feet Number of perfs per linear foot
From feet to feet Number of perfs per linear foot
From feet to feet Number of perfs per linear foot
From feet to feet Number of perfs per linear foot
From feet to feet Number of perfs per linear foot
From feet to feet Number of perfs per linear foot
From feet to feet Number of perfs per linear foot
From feet to feet Number of perfs per linear foot
From feet to feet Number of perfs per linear foot
From feet to feet Number of perfs per linear foot

8 WELL PLUGGING MATERIALS
Material Used

From feet to feet ☐ Pumped ☐ Poured
From feet to feet ☐ Pumped ☐ Poured
From feet to feet ☐ Pumped ☐ Poured
From feet to feet ☐ Pumped ☐ Poured
From feet to feet ☐ Pumped ☐ Poured
From feet to feet ☐ Pumped ☐ Poured

Neat Cement Fluid Weight lbs/gal
Bentonite Grout % bentonite

Date Started 9-Jul
Date Completed 7/9/2015

9 DRILLER'S CERTIFICATION
This well was plugged and abandoned under my supervision and the report is true to the best of my knowledge.

Name Eagle Drilling Services LLC
Contractor
Address 7150 Placid ST
Contractor
Las Vegas NV 89119

Nevada contractor's license number issued by the *State Contractor's Board* 51266
Nevada driller's license number issued by the Division of Water Resources, the *on site driller* 2272
Signed
By driller performing actual drilling on site of contractor
Date 9/24/2015

USE ADDITIONAL SHEETS IF NECESSARY pg. of pg.