

STATE OF NEVADA  
DIVISION OF WATER RESOURCES  
WELL DRILLER'S PLUGGING REPORT

OFFICE USE ONLY  
Log No. 123478  
Permit No. \_\_\_\_\_  
Basin \_\_\_\_\_

PRINT OR TYPE ONLY  
DO NOT WRITE ON BACK

Please complete this form in its entirety in accordance with NRS 534.170 and NAC 534.340

1 OWNER Clark County Public Right - HDW  
MAILING ADDRESS 5003 Grand Central Pl. Las Vegas NV 89155-0000

NOTICE OF INTENT NO. 36849  
ADDRESS AT WELL LOCATION None Public Right-of-Way  
Subdivision Name: \_\_\_\_\_ County Clark

2 LOCATION S 1/4 NE 1/4 Sec 29 T 21 N R 62 E  
PERMIT/WAIVER No. MD-3024 | 161-29-669-014  
Issued by Water Resources Parcel No.

Latitude 36° 05' 34.40" N UTM E  NAD 27  
Longitude -115° 04' 01.95" W  NAD 83/WGS 84

3 TYPE OF WELL  
 Domestic  Irrigation  Test  
 Municipal/Industrial  Monitor  Stock

Is this well being plugged because a replacement well was drilled? NO  
If yes, what is replacement well NOI? \_\_\_\_\_

Is there an existing well log? Yes  
If yes, what is NDWR well log #? unknown

4 EXISTING WELL CONSTRUCTION  
Depth Drilled 40 Feet Depth Cased 40 Feet

7 WELL PLUGGING PROCEDURE  
Was well cleaned out to total depth?  yes  no  
If well was not cleaned out to total depth, please explain why: \_\_\_\_\_

EXISTING CASING SCHEDULE

Size O.D. (Inches)	Weight/FT. (Pounds)	Wall Thickness (Inches)	From (Feet)	To (Feet)
<u>2" sch 40</u>	<u>PVCASTM F. 480</u>	<u>0</u>	<u>0</u>	<u>40</u>

Was the well contaminated?  yes  no  
Was the casing pulled?  yes  no  
Was the casing over drilled?  yes  no  
If casing was left in place, please show where additional perforations were made:

Existing Perforations

Type of perforation	Size of perforation	From	feet to	feet
<u>Factory Slots</u>	<u>020</u>	<u>10</u>	<u>feet to</u>	<u>40</u> feet

Additional Perforations

Type of perforator used:	From	feet to	feet	Number of perfs per linear foot
_____	_____	_____	_____	_____
_____	_____	_____	_____	_____
_____	_____	_____	_____	_____
_____	_____	_____	_____	_____
_____	_____	_____	_____	_____
_____	_____	_____	_____	_____
_____	_____	_____	_____	_____

5 WATER LEVEL  
Static water level \_\_\_\_\_ feet below land surface  
Artesian flow \_\_\_\_\_ G.P.M. P.S.I.  
Water temperature \_\_\_\_\_ °F Quality \_\_\_\_\_

8 WELL PLUGGING MATERIALS

From	feet to	feet	Material Used	<input type="checkbox"/> Pumped	<input type="checkbox"/> Poured
_____	_____	_____	_____	<input type="checkbox"/>	<input type="checkbox"/>
_____	_____	_____	_____	<input type="checkbox"/>	<input type="checkbox"/>
_____	_____	_____	_____	<input type="checkbox"/>	<input type="checkbox"/>
_____	_____	_____	_____	<input type="checkbox"/>	<input type="checkbox"/>
_____	_____	_____	_____	<input type="checkbox"/>	<input type="checkbox"/>
_____	_____	_____	_____	<input type="checkbox"/>	<input type="checkbox"/>

6 Additional Notes or Comments  
Well was destroyed during construction of the Paradise Wharf sewer lateral

DCNR/DWR/SNBO  
RECEIVED  
SEP 24 2015

Neat Cement Fluid Weight \_\_\_\_\_ lbs/gal  
Bentonite Grout \_\_\_\_\_ % bentonite  
Date Started \_\_\_\_\_  
Date Completed \_\_\_\_\_

9 DRILLER'S CERTIFICATION  
This well was plugged and abandoned under my supervision and the report is true to the best of my knowledge.  
Name Elite Drilling Inc. Contractor  
Address 4255 W. Post Rd. Contractor  
Las Vegas NV. 89118  
Nevada contractor's license number 054931  
issued by the State Contractor's Board  
Nevada driller's license number issued by the Division of Water Resources, the on-site driller 1944-M  
Signed Howard Beall  
By driller performing actual drilling on-site or contractor  
Date 9/17/15