

STATE OF NEVADA  
DIVISION OF WATER RESOURCES  
WELL DRILLER'S PLUGGING REPORT

OFFICE USE ONLY  
Log No. 124063  
Permit No. \_\_\_\_\_  
Basin \_\_\_\_\_

PRINT OR TYPE ONLY  
DO NOT WRITE ON BACK

Please complete this form in its entirety in  
accordance with NRS 534.170 and NAC 534.340

NOTICE OF INTENT NO. 39498  
WELL NAME (If applicable): AA-UW5

1 OWNER Richmond American Homes NV, Inc. ADDRESS AT WELL LOCATION 429 Bagatelle Ave.  
MAILING ADDRESS 7770 S. Dean Martin Dr. #308 Henderson, NV 89011  
Las Vegas, NV 89139 Subdivision Name \_\_\_\_\_ County \_\_\_\_\_

2 LOCATION SE 1/4 SW 1/4 Sec 5 T 22S N/S/R 63 E Latitude 36.0570371 UTM E  NAD 27  
PERMIT/WAIVER No. 179-05-413-030 Longitude -114.9676845 N  NAD 83/WGS 84  
Issued by Water Resources Parcel No. \_\_\_\_\_

3 TYPE OF WELL  
 Domestic  Irrigation  Test  
 Municipal/Industrial  Monitor  Stock  
Is this well being plugged because a replacement well was drilled? NO  
If yes, what is replacement well NOI? \_\_\_\_\_  
Is there an existing well log? \_\_\_\_\_  
If yes, what is NDWR well log #? \_\_\_\_\_

4 EXISTING WELL CONSTRUCTION  
Depth Drilled \_\_\_\_\_ Feet Depth Cased 61 Feet  
EXISTING CASING SCHEDULE  
Size O.D. (Inches) Weight/Ft. (Pounds) Wall Thickness (Inches) From (Feet) To (Feet)  
4 PVC SCH 40 \_\_\_\_\_ \_\_\_\_\_  
\_\_\_\_\_ \_\_\_\_\_ \_\_\_\_\_ \_\_\_\_\_ \_\_\_\_\_  
\_\_\_\_\_ \_\_\_\_\_ \_\_\_\_\_ \_\_\_\_\_ \_\_\_\_\_  
\_\_\_\_\_ \_\_\_\_\_ \_\_\_\_\_ \_\_\_\_\_ \_\_\_\_\_  
\_\_\_\_\_ \_\_\_\_\_ \_\_\_\_\_ \_\_\_\_\_ \_\_\_\_\_

7 WELL PLUGGING PROCEDURE  
Was well cleaned out to total depth?  yes  no  
If well was not cleaned out to total depth, please explain why: \_\_\_\_\_  
Was the well contaminated?  yes  no  
Was the casing pulled?  yes  no If pulled from: \_\_\_\_\_ feet to \_\_\_\_\_ feet  
Was the casing over drilled?  yes  no  
If casing was left in place, please show where additional perforations were made:  
Additional Perforations: \_\_\_\_\_  
Type of perforater used: \_\_\_\_\_

Existing Perforations:  
Type of perforation \_\_\_\_\_  
Size of perforation \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet

From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_

5 WATER LEVEL  
Static water level 47 feet below land surface  
Artesian flow \_\_\_\_\_ G.P.M. \_\_\_\_\_ P.S.I. \_\_\_\_\_  
Water temperature 77 °F Quality \_\_\_\_\_

6 Additional Notes or Comments  
\_\_\_\_\_

\*\*ATTEMPTED TO PULL CASING. CASING BROKE OFF AT 2 FEET BGS. PROCEEDED TO KNOCK OUT BOTTOM CAP AND PRESSURE GROUT FROM BOTTOM TO TOP.\*\*

8 WELL PLUGGING MATERIALS  
Material Used  
From 61 feet to 0 feet BENTONITE GROUT  Pumped  Poured  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet  Pumped  Poured  
Neat Cement Fluid Weight \_\_\_\_\_ lbs/gal  
Bentonite Grout 28 % bentonite

Date Started 11/11/2015  
Date Completed 11/11/2015

9 DRILLER'S CERTIFICATION  
This well was plugged and abandoned under my supervision and the report is true to the best of my knowledge.  
Name EAGLE DRILLING SERVICES, LLC. Contractor  
Address 7150 PLACID ST. LAS VEGAS, NV 89119 Contractor  
Nevada contractor's license number \_\_\_\_\_  
issued by the State Contractor's Board 51266  
Nevada driller's license number issued by the Division of Water Resources, the on-site driller 2490-LTD  
Signed [Signature]  
By driller performing well drilling on site or contractor  
Date 11/12/2015

DNWR/DWR/SNBO  
RECEIVED  
NOV 17 2015

36.0570607  
-114.9668587  
NAD  
27