

October 2, 2008

State of Nevada
State Engineer
400 Shadow Lane, No. 201
Las Vegas, Nevada 89195

Re: Request for Monitoring Well Abandonment
Sav-Mor Car Rental Facility
5101 Rent-A-Car Road
Las Vegas, Nevada
Terracon Project No. 64077106

Dear Sir/Madam:

This correspondence is to detail the destruction of an existing monitoring well at the Sav-Mor Car Rental Facility property located at 5101 Rent-A-Car Road, Las Vegas, Nevada. A monitoring well, designated as MW-1, was destroyed during roto-milling and paving activities at the subject site between June and August, 2008. The monitoring well was originally installed on September 28, 2007 under the supervision of Matt Halmond, a Terracon Environmental Professional (see attached NVDWR documentation).

The well casing was destroyed by heavy equipment during the asphalt grinding process. The area was subsequently compacted and paved over. The well casing could not be located and excavation of the area was not possible. It was determined that the upper portion of the casing has been pulverized and crushed.

Terracon requests that this well (Log #103920) be revised as abandoned by the NVDWR.

Please contact either of the undersigned at (702) 597-9393 if you have questions regarding the information provided in the report.


Sincerely,
Terracon

Prepared by:

Reviewed by:

Michael P. Nelson, P.G., C.E.M.
Environmental Project Geologist

Michael K. Nibert, CHMM, C.E.M.
Environmental Operations Manager
(C.E.M.-2059, Expires 03/01/09)



Home	State Home Pages	About Us	Publications
Website Questions			




State of Nevada
 Department of Conservation & Natural Resources
Division of Water Resources
 Tracy Taylor, P. E. State Engineer

Well Driller's Log Database: Report Details

GENERAL INFORMATION			
Well Log No: 103920	Sequence No: 103238	Permit No:	Basin: 212
Click Here To View an Image of The Original Well Log			
Owner: CLARK COUNTY AVIATION	Mailing/Well Address: 5101 RENT A CAR RD	Owner No.: MW-03	Notice of Intent No.: 31481
Date Received by NDWR: 10/02/2007	Date Accessed: D	Entered By/Date: SGARDELLA 11/27/2007	Updated By/Date: SGARDELLA 11/27/2007

LOCATION INFORMATION				
Quarters: BD	Section: 27	Township: S21	Range: E61	Ref: MD
Latitude: 36.0952777778	Longitude: 115.146944444	Lat/Long Accuracy: M	Parcel No.: 162-27-201-002	Lot No.:
State/Co. Code: 32003	Type of Work: N	Source Agency: NV003	Subdivision Name:	Block No.:

WELL CONSTRUCTION				
Hole Depth: 30 feet	Surface Casing Dia.: 2.0 Inches	Cased to: 30 feet	Casing Reductions: 0	Depth to Bedrock: feet
Perforations: 15 to 30 feet	Perforation Length: 15 feet	Perforation Intervals: 1	Depth of Seal: 13 feet	Construction Date:



Gravel Packed: YFrom: 13 to 30 feet		Static Water Level: 19.00 ft below LSD	Pumping Water Level: feet	Draw Down: feet
Yield: G.P.M.	After Hours Pump:	Aquifer Desc.	Specific Capacity: 0.00	Lithographic Data Quality: G
Method:	Date Started: 09/28/2007	Date Completed: 09/28/2007	Water Temp: deg F	Edit Status: F
Work Type Remarks:				
General Remarks:				
Additional Remarks:				
DRILLING CONTRACTOR INFORMATION				
Name: EAGLE DRILLING SERVICES LLC	Address: 7150 PLACID STREET LAS VEGAS NV 89119	Contractor's Lic. No.: 51266	Contractor's Drilling No.:	Driller's Lic. No.: 2272

