

STATE OF NEVADA
DIVISION OF WATER RESOURCES
WELL DRILLER'S PLUGGING REPORT

OFFICE USE ONLY
Log No. 124299
Permit No. _____
Basin 087

PRINT OR TYPE ONLY
DO NOT WRITE ON BACK

Please complete this form in its entirety in accordance with NRS 534.170 and NAC 534.340

NOTICE OF INTENT NO. 72102
WELL NAME (if applicable): INT-32-2

1 OWNER Vista Canyon Group
MAILING ADDRESS PO box 281304
Lakewood, CO 80228

ADDRESS AT WELL LOCATION 255 S Stanton Way
Sparks, NV 89431
Subdivision Name _____ County Washoe

2 LOCATION NW 1/4 Sec 19 T 19 O S R 20 E
PERMIT/WAIVER No. UPRR ROW
Issued by Water Resources Parcel No.

Latitude 39° 31' 53.45" N UTM E NAD 27
Longitude 119° 44' 52.02" W N NAD 83/WGS 84

3 TYPE OF WELL
 Domestic Irrigation Test
 Municipal/Industrial Monitor Stock

Is this well being plugged because a replacement well was drilled? NO
If yes, what is replacement well NOI? _____

Is there an existing well log? _____
If yes, what is NDWR well log #? _____

4 EXISTING WELL CONSTRUCTION
Depth Drilled 50 Feet Depth Cased 50 Feet

7 WELL PLUGGING PROCEDURE
Was well cleaned out to total depth? yes no
If well was not cleaned out to total depth, please explain why: _____

| Size O.D. (Inches) | Weight/Ft. (Pounds) | Wall Thickness (Inches) | From (Feet) | To (Feet) |
|--------------------|---------------------|-------------------------|-------------|-----------|
| <u>2"</u> | | <u>SCH 40 PVC</u> | <u>0</u> | <u>48</u> |
| | | | | |
| | | | | |
| | | | | |

Was the well contaminated? yes no
Was the casing pulled? yes no If pulled from: _____ feet to _____ feet
Was the casing over drilled? yes no

Existing Perforations:
Type of perforation Slotted
Size of perforation .040
From 48 feet to 50 feet
From _____ feet to _____ feet
From _____ feet to _____ feet
From _____ feet to _____ feet

If casing was left in place, please show where additional perforations were made:
Additional Perforations:
Type of perforator used:
From _____ feet to _____ feet Number of perfs per linear foot _____
From _____ feet to _____ feet Number of perfs per linear foot _____
From _____ feet to _____ feet Number of perfs per linear foot _____
From _____ feet to _____ feet Number of perfs per linear foot _____
From _____ feet to _____ feet Number of perfs per linear foot _____
From _____ feet to _____ feet Number of perfs per linear foot _____
From _____ feet to _____ feet Number of perfs per linear foot _____
From _____ feet to _____ feet Number of perfs per linear foot _____
From _____ feet to _____ feet Number of perfs per linear foot _____
From _____ feet to _____ feet Number of perfs per linear foot _____
From _____ feet to _____ feet Number of perfs per linear foot _____
From _____ feet to _____ feet Number of perfs per linear foot _____

5 WATER LEVEL
Static water level 19 feet below land surface
Artesian flow _____ G.P.M. _____ P.S.I.
Water temperature _____ °F Quality _____

6 Additional Notes or Comments
Pumped cement grout
from bottom of well
to surface, removed
MONUMENT

NAD 27
39.531611° N
119.746762° W

8 WELL PLUGGING MATERIALS
Material Used
From 50 feet to 0 feet Cement grout Pumped Poured
From _____ feet to _____ feet Pumped Poured
Neat Cement Fluid Weight 147 lbs/gal
Bentonite Grout _____ % bentonite
Date Started 12/10/15
Date Completed 12/10/15

9 DRILLER'S CERTIFICATION
This well was plugged and abandoned under my supervision and the report is true to the best of my knowledge.
Name Environmental West Exploration Contractor
Address PO box 11095 Sparks Valley WA Contractor 99211
Nevada contractor's license number issued by the State Contractor's Board 0028363
Nevada driller's license number issued by the Division of Water Resources, the on-site driller 2424-M
Signed _____
By driller performing actual drilling on site of contractor
Date 1/6/16

Plugs Unknown well log