

STATE OF NEVADA  
DIVISION OF WATER RESOURCES  
WELL DRILLER'S PLUGGING REPORT

OFFICE USE ONLY  
Log No. 124301  
Permit No. \_\_\_\_\_  
Basin 087

PRINT OR TYPE ONLY  
DO NOT WRITE ON BACK

Please complete this form in its entirety in accordance with NRS 534.170 and NAC 534.340

NOTICE OF INTENT NO. 72102  
WELL NAME (if applicable): 255-JR-4

1 OWNER Vista Canyon Group  
MAILING ADDRESS PO Box 281304  
Lakewood, CO 80228

ADDRESS AT WELL LOCATION 255 S Starbuck Way  
Sparks, NV 89431  
Subdivision Name \_\_\_\_\_ County WASHOE

2 LOCATION NW 1/4 NE 1/4 Sec 9 T19 N R 20 E  
PERMIT/WAIVER No. UPRR Row  
Issued by Water Resources Parcel No. \_\_\_\_\_

Latitude 39° 31' 53.25" N JTM E  NAD 27  
Longitude 119° 41' 50.91" W N  NAD 83/WGS 84

3 TYPE OF WELL  
 Domestic  
 Municipal/Industrial  
 Irrigation  
 Monitor  
 Test  
 Stock

Is this well being plugged because a replacement well was drilled? NO  
If yes, what is replacement well NOI? \_\_\_\_\_

Is there an existing well log? \_\_\_\_\_  
If yes, what is NDWR well log #? \_\_\_\_\_

4 EXISTING WELL CONSTRUCTION  
Depth Drilled 50 Feet Depth Cased 50 Feet

7 WELL PLUGGING PROCEDURE  
Was well cleaned out to total depth?  yes  no  
If well was not cleaned out to total depth, please explain why: \_\_\_\_\_

Size O.D. (Inches)	Weight/Ft. (Pounds)	Wall Thickness (Inches)	From (Feet)	To (Feet)
<u>2"</u>		<u>5/16" PVC</u>	<u>0</u>	<u>48</u>

Was the well contaminated?  yes  no  
Was the casing pulled?  yes  no If pulled from: \_\_\_\_\_ feet to \_\_\_\_\_ feet  
Was the casing over drilled?  yes  no  
If casing was left in place, please show where additional perforations were made:  
Additional Perforations: \_\_\_\_\_

Existing Perforations:  
Type of perforation Slotted  
Size of perforation 1.040  
From 48 feet to 50 feet  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet

Type of perforator used:  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_

5 WATER LEVEL  
Static water level 18 feet below land surface  
Artesian flow \_\_\_\_\_ G.P.M. \_\_\_\_\_ P.S.I.  
Water temperature \_\_\_\_\_ °F Quality \_\_\_\_\_

6 Additional Notes or Comments  
Pumped Cement grout  
From bottom of well  
to surface removed  
movement  
  
NAD 27  
39.531547° N  
119.746453° W

8 WELL PLUGGING MATERIALS  
Material Used  
From 50 feet to 0 feet Cement grout  Pumped  Paired  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet  Pumped  Paired  
Neat Cement Fluid Weight 14 lbs/gal  
Bentonite Grout \_\_\_\_\_ % bentonite  
Date Started 12/10/15  
Date Completed 12/10/15

9 DRILLER'S CERTIFICATION  
This well was plugged and abandoned under my supervision and the report is true to the best of my knowledge.  
Name Environmental West Exploration  
Address PO box 11095 Sparks Valley WA 99211  
Nevada contractor's license number 0028763  
issued by the State Contractor's Board  
Nevada driller's license number issued by the Division of Water Resources, the on-site driller 2929-M  
Signed \_\_\_\_\_  
By driller performing actual drilling on site or contractor  
Date 1/6/16

Plugs Unknown Well log