STATE OF NEVADA
DIVISION OF WATER RESOURCES
WELL DRILLER'S PLUGGING REPORT

OFFICE USE ONLY
Log No. 124628
Permit No.
Basin

PRINT OR TYPE ONLY
DO NOT WRITE ON BACK

Please complete this form in its entirety in accordance with NRS 534.170 and NAC 534.340

NOTICE OF INTENT NO. 39488
WELL NAME *(if applicable)*: MW-13

1 OWNER Paradise Gardens Shopping Center / Adams
MAILING ADDRESS 18321 Ventura Blvd.
Tarzana, CA 91356-4228

ADDRESS AT WELL LOCATION 1131 E. TROPICANA AVE.
LAS VEGAS, NV 89119
Subdivision Name: *County:* Clark

2 LOCATION NE ¼ NE ¼ Sec 27 T 21S N/S R 61 E
PERMIT/WAIVER No. 162-27-502-004
Issued by Water Resources *Parcel No.*

Latitude 36.100473
Longitude -115.137751
UTM E
N
☐ NAD 27
☒ NAD 83/WGS 8

3 TYPE OF WELL
☐ Domestic ☐ Irrigation ☐ Test
☐ Municipal/Industrial ☒ Monitor ☐ Stock

Is this well being plugged because a replacement well was drilled? NO
If yes, what is replacement well NO!?

Is there an existing well log?
If yes, what is NDWR well log #?

4 *EXISTING WELL CONSTRUCTION*
Depth Drilled Feet Depth Cased 70 Feet

EXISTING CASING SCHEDULE

Size O.D. (Inches)	Weight/Ft. (Pounds)	Wall Thickness (Inches)	From (Feet)	To (Feet)
2	PVC	SCH 40	0	70

Existing Perforations:
Type of perforation MACHINE SLOTTED
Size of perforation 0.02

From	65	feet to	70 feet
From		feet to	feet
From		feet to	feet
From		feet to	feet
From		feet to	feet

5 *WATER LEVEL*
Static water level 12.5 feet below land surface
Artesian flow G.P.M. P.S.I
Water temperature 77 °F Quality

6 Additional Notes or Comments

DCNR/DWR/SNBO
RECEIVED
FEB 12 2016

7 WELL PLUGGING PROCEDURE
Was well cleaned out to total depth? ☒ yes ☐ no
If well was not cleaned out to total depth, please explain why:

Was the well contaminated? ☐ yes ☒ no
Was the casing pulled? ☒ yes ☐ no If pulled from: 0 feet to 70 feet
Was the casing over drilled? ☐ yes ☒ no
If casing was left in place, please show where additional perforations were made:
Additional Perforations:
Type of perforator used:

From	feet to	feet	Number of perfs per linear foot	
From	feet to	feet	Number of perfs per linear foot	
From	feet to	feet	Number of perfs per linear foot	
From	feet to	feet	Number of perfs per linear foot	
From	feet to	feet	Number of perfs per linear foot	
From	feet to	feet	Number of perfs per linear foot	
From	feet to	feet	Number of perfs per linear foot	
From	feet to	feet	Number of perfs per linear foot	
From	feet to	feet	Number of perfs per linear foot	
From	feet to	feet	Number of perfs per linear foot	
From	feet to	feet	Number of perfs per linear foot	
From	feet to	feet	Number of perfs per linear foot	

8 WELL PLUGGING MATERIALS

				Material Used		
From	70 feet to	1 feet	BENTONITE GROUT	☒ Pumped	☐ Poured
From	1 feet to	0 feet	CONCRETE	☐ Pumped	☒ Poured
From	feet to	feet		☐ Pumped	☐ Poured
From	feet to	feet		☐ Pumped	☐ Poured
From	feet to	feet		☐ Pumped	☐ Poured
From	feet to	feet		☐ Pumped	☐ Poured

Neat Cement Fluid Weight lbs/gal
Bentonite Grout 28 % bentonite
Date Started 10/1/2015
Date Completed 10/1/2015

9 DRILLER'S CERTIFICATION
This well was plugged and abandoned under my supervision and the report is true to the best of my knowledge.
Name EAGLE DRILLING SERVICES
Contractor
Address 7150 PLACID ST. LAS VEGAS, NV 89119
Contractor

Nevada contractor's license number issued by the *State Contractor's Board* 51266
Nevada driller's license number issued by the Division of Water Resources, the *on-site driller* 2490-LTD
Signed
By driller performing actual drilling on site or contractor
Date 10/6/2015

(Rev 12/13)
USE ADDITIONAL SHEETS IF NECESSARY pg. of pg.

NAD 27 36.1005000
-115.1369196