STATE OF NEVADA
DIVISION OF WATER RESOURCES
WELL DRILLER'S PLUGGING REPORT

OFFICE USE ONLY
Log No. 124772
Permit No.
Basin

PRINT OR TYPE ONLY
DO NOT WRITE ON BACK

Please complete this form in its entirety in accordance with NRS 534.170 and NAC 534.340

NOTICE OF INTENT NO. 38925
WELL NAME (If applicable):

1 OWNER State of Nevde % Div of state Lands
MAILING ADDRESS 901 s Stewart St #5003
Carson City Nv 89701

ADDRESS AT WELL LOCATION 2621 E Sahara Ave
Las Vegas Nv
Subdivision Name: County: Clark

2 LOCATION SE ¼ SW ¼ Sec 1 T 21S N/S R 61 E
PERMIT/WAIVER No. 162-01-401-008
Issued by Water Resources Parcel No.

Latitude 36.145976
Longitude -115.114065
UTM E
N
☐ NAD 27
☒ NAD 83/WGS 8

3 TYPE OF WELL
☒ Domestic ☐ Irrigation ☐ Test
☐ Municipal/Industrial ☐ Monitor ☐ Stock

Is this well being plugged because a replacement well was drilled?
If yes, what is replacement well NO!?

Is there an existing well log? no
If yes, what is NDWR well log #?

4 EXISTING WELL CONSTRUCTION
Depth Drilled Feet Depth Cased 24 Feet

EXISTING CASING SCHEDULE

Size O.D. (Inches)	Weight/Ft. (Pounds)	Wall Thickness (Inches)	From (Feet)	To (Feet)
6.		.10	0	24

Existing Perforations:
Type of perforation
Size of perforation
From feet to feet
From feet to feet
From feet to feet
From feet to feet
From feet to feet

5 WATER LEVEL
Static water level Artesian feet below land surface
Artesian flow 5 G.P.M. P.S.I
Water temperature 78 °F Quality

6 Additional Notes or Comments

When we ran camera we only Found 24 of casing

Hole was open to 225

Filled with cement Grout
Tremied From Bottom to Top

DCNR/DWR/SNBO
RECEIVED
JAN 29 2016

7 WELL PLUGGING PROCEDURE
Was well cleaned out to total depth? ☒ yes ☐ no
If well was not cleaned out to total depth, please explain why:

Was the well contaminated? ☐ yes ☒ no
Was the casing pulled? ☐ yes ☒ no If pulled from: feet to feet
Was the casing over drilled? ☐ yes ☒ no
If casing was left in place, please show where additional perforations were made:

Additional Perforations.
Type of perforater used:
From feet to feet Number of perfs per linear foot
From feet to feet Number of perfs per linear foot
From feet to feet Number of perfs per linear foot
From feet to feet Number of perfs per linear foot
From feet to feet Number of perfs per linear foot
From feet to feet Number of perfs per linear foot
From feet to feet Number of perfs per linear foot
From feet to feet Number of perfs per linear foot
From feet to feet Number of perfs per linear foot
From feet to feet Number of perfs per linear foot
From feet to feet Number of perfs per linear foot
From feet to feet Number of perfs per linear foot

8 WELL PLUGGING MATERIALS
Material Used
From 0 feet to 225 feet ☒ Pumped ☐ Poured
From feet to feet ☐ Pumped ☐ Poured
From feet to feet ☐ Pumped ☐ Poured
From feet to feet ☐ Pumped ☐ Poured
From feet to feet ☐ Pumped ☐ Poured
From feet to feet ☐ Pumped ☐ Poured
Neat Cement Fluid Weight lbs/gal
Bentonite Grout % bentonite
Date Started 1/4/2016
Date Completed 1/26/2016

9 DRILLER'S CERTIFICATION
This well was plugged and abandoned under my supervision and the report is true to the best of my knowledge.
Name Eagle Drilling Services (Contractor)
Address 7150 Placid Steet (Contractor)
Las Vegas Nv
Nevada contractor's license number issued by the State Contractor's Board 51266
Nevada driller's license number issued by the Division of Water Resources the on-site driller 2097
Signed (By driller performing actual drilling on site or contractor)
Date 1/28/2016

USE ADDITIONAL SHEETS IF NECESSARY pg. of pg.

(Rev 12-13)

36.160043
-115.1132324
NAD 27