

Log No. 20206

Permit No. _____

Basin _____

WELL DRILLERS REPORT

Please complete this form in its entirety.

1. OWNER Tom Poulas ADDRESS Lot #2 Davis Creek Subdivision

2. LOCATION NW 1/4 NW 1/4 Sec. 34 T. 17N R. 19 E. WASHOE County
 PERMIT NO. 850

3. TYPE OF WORK
 New Well Recondition
 Deepen Other
 4. PROPOSED USE
 Domestic Irrigation Test
 Municipal Industrial Stock
 5. TYPE WELL
 Cable Rotary
 Other

6. LITHOLOGIC LOG

Material	Water Strata	From	To	Thick-ness
TOPSOIL	<input checked="" type="checkbox"/>	0	1	
D-G SAND & BOULDERS		1	18	
BROWN SANDY CLAY		18	32	
D.G. SANDS		32	59	
SAND & CLAY		59	66	
COARSE GRAVEL & SAND	<input checked="" type="checkbox"/>	66	69	
D.G. SAND	<input checked="" type="checkbox"/>	69	78	
SANDY CLAY		78	80	

8. 12" to 50" WELL CONSTRUCTION
 Diameter hole 8 7/8 inches Total depth 80 feet
 Casing record _____
 Weight per foot 16.94 Thickness 1.88
 Diameter 8 7/8 inches From 0 feet To 80 feet
 _____ inches _____ feet _____ feet
 Surface seal: Yes No Type CEMENT
 Depth of seal 50 feet
 Gravel packed: Yes No
 Gravel packed from _____ feet to _____ feet
 Perforations:
 Type perforation torch cut
 Size perforation 3/32 x 4"
 From 58 feet to 78 feet
 From _____ feet to _____ feet

9. WATER LEVEL
 Static water level 16 Feet below land surface
 Flow _____ G.P.M. 25
 Water temperature COLD ° F. Quality GOOD

Date started JUNE 12, 1979
 Date completed JUNE 15, 1979

7. WELL TEST DATA

Pump RPM	G.P.M.	Draw Down	After Hours Pump

10. DRILLERS CERTIFICATION
 This well was drilled under my supervision and the report is true to the best of my knowledge.
 Name Labrum's Drilling
 Address P.O. 543 Dayton, Nevada
 Nevada contractor's license number 14020
 Nevada driller's license number 662
 Signed Terry Bergstad
 Date JUNE 15, 1979

BAILER TEST
 G.P.M. 25 g.p.m. Draw down _____ feet _____ hours
 G.P.M. _____ Draw down _____ feet _____ hours
 G.P.M. _____ Draw down _____ feet _____ hours