

WELL DRILLERS REPORT

Please complete this form in its entirety

1. OWNER Bob Marine ADDRESS 3467 Boyer Rd.

2. LOCATION SW 1/4 NW 1/4 Sec 8 T 18 N/S R. 23 E Churchill County
 PERMIT NO.

3. TYPE OF WORK
 New Well Recondition
 Deepen Other
 4. PROPOSED USE
 Domestic Irrigation Test
 Municipal Industrial Stock
 5. TYPE WELL
 Cable Rotary
 Other

6. LITHOLOGIC LOG

Material	Water Strata	From	To	Thick-ness
Sand	⊕	0	25	25
Sandy Clay		25	35	10
Sand & Gravel	✓	35	47	12
Clay		47	48	1
Sand & Gravel	✓	48	60	12
Clay		60	-	-

8. WELL CONSTRUCTION
 Diameter hole 8 inches Total depth 60 feet
 Casing record
 Weight per foot Thickness 188
 Diameter From To
8 inches 0 feet 60 feet
 inches feet feet
 Surface seal: Yes No Type Cement
 Depth of seal feet
 Gravel packed: Yes No
 Gravel packed from 48 feet to 60 feet
 Perforations:
 Type perforation Torch Cut
 Size perforation 3/16
 From 53 feet to 60 feet
 From feet to feet

Date started May 26, 1980
 Date completed May 30, 1980

7. WELL TEST DATA

Pump RPM	G.P.M.	Draw Down	After Hours Pump
Well	Hit	Jetted @	30 GPM

BAILER TEST

G.P.M.	Draw down	feet	hours
.....
.....
.....

9. WATER LEVEL
 Static water level 54 Feet below land surface 6
 Flow 2" G.P.M. 30
 Water temperature Cold F. Quality Good

10. DRILLERS CERTIFICATION
 This well was drilled under my supervision and the report is true to the best of my knowledge.
 Name Paul N Pflimlin
 Address 7007 Curry Rd.
 Nevada contractor's license number
 Nevada driller's license number 928
 Signed Paul N. Pflimlin
 Date May 31, 1980