WHITE—DIVISION OF WATER RESOURCES
CANARY—CLIENT'S COPY
PINK—WELL DRILLER'S COPY

STATE OF NEVADA
DIVISION OF WATER RESOURCES

WELL DRILLERS REPORT

Please complete this form in its entirety

OFFICE USE ONLY (page #1)
Log No. 21589
Permit No. 36330
Basin 108

#1/2 FINALIZED 44

1. OWNER RICHARD HOLBROOK ADDRESS 46 PURSEL LN.
YERINGTON, NEV. 89447
new apn# 12-161-13 ★ SEE RECONDITIONING LOG #110416

2. LOCATION SE ¼ SE ¼ Sec. 31 T. 13 N/S R. 26 E. LYON County
PERMIT NO. 36330 38.939.762°N NAD27 D.D. 119.106.885°W

3. TYPE OF WORK
New Well ☒ Recondition ☐
Deepen ☐ Other ☐

4. PROPOSED USE
Domestic ☐ Irrigation ☒ Test ☐
Municipal ☐ Industrial ☐ Stock ☐

5. TYPE WELL
Cable ☐ Rotary ☒
Other ☐

6. LITHOLOGIC LOG

Material	Water Strata	From	To	Thickness
TOP SOIL SANDY		0	3	3
COARSE SAND + GRAVEL VOLCANIC		3	25	22
COARSE SAND + GRAVEL + CLAY		25	30	5
COARSE SAND, GRAVEL VOLCANIC	X	30	100	70
COARSE SAND, GRAVEL VOLCANIC ROCK	X	100	102	2
COARSE SAND, GRAVEL VOL.	X	102	105	3
COARSE SAND, GRAVEL VOL. ROCK	X	105	110	5
COARSE SAND + GRAVEL VOLCANIC	X	110	117	7
SOILD ROCK VOL.		117	120	3
VOL. FILL	X	120	122	2
SOILD ROCK VOL.		122	124	2
SOILD ROCK W/CRACKS DECOMPOSED GRAINITE	X	124	155	31
SOILD ROCK W/CRACKS W/RED CLAY D.G.		155	170	15
SOILD ROCK W/CRACKS D.G.	X	170	180	10
SOILD ROCK W/CRACKS/W RED CLAY W D.G.		180	190	10
SOILD ROCK W/CRACKS D.G.	X	190	200	10
SOILD ROCK W/CRACKS W/RED CLAY		200	204	4
SOILD ROCK W/CRACKS D.G.	X	204	208	4
CONT ON NEXT SHEET.				

Date started AUG 6, 1980
Date completed AUG 27, 1980

7. WELL TEST DATA

Pump RPM	G.P.M.	Draw Down	After Hours Pump
1900	1344	91'6"	18 HR
RECOVERY TIME FROM 1[illegible] TO 50' IS 2 MIN.			
SEPT 9-13 1980 TEST PUMPED			

BAILER TEST
G.P.M. 100 Draw down 10 feet 1/2 hours
G.P.M. Draw down feet hours
G.P.M. Draw down feet hours

8. WELL CONSTRUCTION
Diameter hole 24" inches Total depth 203'6" feet
Casing record 11" 203'6" TO 311'9"
Weight per foot Thickness .250 .188
16" 6"

Diameter	From	To
16" inches	(+) 2' feet	201'6" feet
6 5/8" inches	201'6" feet	309'9" feet
inches	feet	feet
inches	feet	feet
inches	feet	feet
inches	feet	feet

Surface seal: Yes ☐ No ☒ Type N/A
Depth of seal N/A feet
Gravel packed: Yes ☒ No ☐
Gravel packed from 0' feet to 309'9" feet

Perforations:
Type perforation SAWED
Size perforation 3/32" x 3"
From 62' feet to 309'9" feet
From feet to feet
From feet to feet
From feet to feet
From feet to feet

9. WATER LEVEL
Static water level 48'6" Feet below land surface 40'6"
Flow — G.P.M. —
Water temperature COLD ° F. Quality GOOD

10. DRILLERS CERTIFICATION
This well was drilled under my supervision and the report is true to the best of my knowledge.

Name OGDEN BROS' DRILLING
Address 162 N. BYBEE LN YERINGTON NEV. 89447
Nevada contractor's license number 15646
Nevada driller's license number 830
Signed [signature]
Date 10/13/80

USE ADDITIONAL SHEETS IF NECESSARY

O-627

WHITE—DIVISION OF WATER RESOURCES
CANARY—CLIENT'S COPY
PINK—WELL DRILLER'S COPY

#2/2 FINALIZED MA

STATE OF NEVADA
DIVISION OF WATER RESOURCES

WELL DRILLERS REPORT

Please complete this form in its entirety

OFFICE USE ONLY
Log No. 21589 (page #2)
Permit No. 36330
Basin 108

1. OWNER RICHARD HOLBROOK ADDRESS 46 PURSEL LN.
new gpm# 12-161-13 * SEE RECONDITIONING LOG #110416
2. LOCATION SE ¼ SE ¼ Sec. 31 T. 13N N/S R. 26 E. LYON County
PERMIT NO. 36 330 38.939,762°N NAD27 D.D. 119.106,885°W

3. TYPE OF WORK
New Well ☒ Recondition ☐
Deepen ☐ Other ☐

4. PROPOSED USE
Domestic ☐ Irrigation ☒ Test ☐
Municipal ☐ Industrial ☐ Stock ☐

5. TYPE WELL
Cable ☐ Rotary ☒
Other ☐

6. LITHOLOGIC LOG

Material	Water Strata	From	To	Thickness
SOLID ROCK w/ CRACKS w/ RED CLAY D.G.		208	218	10
SOLID ROCK w/ CRACKS	X	218	220	2
SOLID ROCK w/ CRACKS w/ RED CLAY		220	222	2
SOLID ROCK w/ CRACKS D.G.	X	222	224	2
SOLID ROCK w/ CRACKS w/ CLAY		224	230	6
SOILD ROCK w/ CRACKS D.G.	X	230	240	10
SOILD ROCK w/ CRACKS/ w/ CLAY RED D.G.		240	242	2
SOILD ROCK w/ CRACKS D.G.	X	242	245	3
SOILD ROCK w/ CRACKS w/ CLAY RED		245	248	3
SOILD ROCK w/ CRACKS D.G.	X	248	250	2
SOILD ROCK w/ CRACKS w/ CLAY RED		250	262	12
SOLID ROCK NO CRACKS		262	275	13
SOILD ROCK w/ CRACKS w/ CLAY RED		275	280	5
BROKEN ROCK w/ CLAY RED		280	282	2
SOILD ROCK w/ CRACKS w/ WHITE CLAY		282	284	2
BROKEN ROCK w/ RED CLAY		284	287	3
SOLID ROCK w/ CRACKS + RED CLAY		287	305	18
SOILD ROCK w/ CRACKS	X	305	309	4

Date started AUG 6, 1980
Date completed AUG 29, 1980

7. WELL TEST DATA

Pump RPM	G.P.M.	Draw Down	After Hours Pump
SEPT 9 - 13	1980	TEST	PUMPED

BAILER TEST
G.P.M. ..... Draw down ..... feet ..... hours
G.P.M. ..... Draw down ..... feet ..... hours
G.P.M. ..... Draw down ..... feet ..... hours

8. WELL CONSTRUCTION
Diameter hole ..... inches Total depth ..... feet
Casing record .....
Weight per foot ..... Thickness .....

Diameter	From	To
..... inches	..... feet	..... feet
..... inches	..... feet	..... feet
..... inches	..... feet	..... feet
..... inches	..... feet	..... feet
..... inches	..... feet	..... feet
..... inches	..... feet	..... feet

Surface seal: Yes ☐ No ☐ Type .....
Depth of seal ..... feet
Gravel packed: Yes ☐ No ☐
Gravel packed from ..... feet to ..... feet

Perforations:
Type perforation .....
Size perforation .....
From ..... feet to ..... feet
From ..... feet to ..... feet
From ..... feet to ..... feet
From ..... feet to ..... feet
From ..... feet to ..... feet

9. WATER LEVEL
Static water level ..... Feet below land surface .....
Flow ..... G.P.M. .....
Water temperature ..... ° F. Quality .....

10. DRILLERS CERTIFICATION
This well was drilled under my supervision and the report is true to the best of my knowledge.

Name [signature]
Address 1ER N. BYBEE LN. YERINGTON NEV. 89447
Nevada contractor's license number 15646
Nevada driller's license number 820
Signed [signature]
Date 10/18/80

USE ADDITIONAL SHEETS IF NECESSARY

O-627