

Log No. 24361
 Permit No. DOU16577C
 Basin _____

WELL DRILLERS REPORT

Please complete this form in its entirety

NOTICE OF INTENT NO. 1326

PRINT OR TYPE ONLY

1. OWNER LARRY Strickland ADDRESS AT WELL LOCATION EAST Valley Rd & Buckeye
 MAILING ADDRESS Clapham
Minden, Nev.

2. LOCATION $\frac{1}{4}$ Sec. 23 T. 13 S. R. 20 E. Douglas County
 PERMIT NO. 23-290-30 Issued by Water Resources Parcel No. _____ Subdivision Name _____

3. TYPE OF WORK
 New Well Recondition
 Deepen Other

4. PROPOSED USE
 Domestic Irrigation
 Municipal Industrial

5. TYPE WELL
 Cable Rotary
 Other

6. LITHOLOGIC LOG

Material	Water Strata	From	To	Thick-ness
Clay & sand		0	44	
Clay & Cobble stones		44	56	
Clay & sand	x	56	58	
Clay		58	103	
Sand & some clay	x	103	126	
Clay	x	126	130	

8. WELL CONSTRUCTION
 Diameter hole 8 5/8 inches Total depth 130 feet
 Casing record 130
 Weight per foot _____ Thickness 188
 Diameter 8 5/8 inches From 0 feet To 130 feet
 _____ inches _____ feet _____ feet

Surface seal: Yes No Type Cement
 Depth of seal 50' feet
 Gravel packed: Yes No
 Gravel packed from _____ feet to _____ feet

Perforations:
 Type perforation Factory slot
 Size perforation 3x 7/16
 From 105 feet to 125 feet
 From _____ feet to _____ feet

9. WATER LEVEL
 Static water level 35 feet below land surface
 Flow _____ G.P.M. 20 P.S.I.
 Water temperature _____ ° F. Quality _____

Date started 12-3- 1982
 Date completed 12-7- 1982

7. WELL TEST DATA

Pump RPM	G.P.M.	Draw Down	After Hours Pump

10. DRILLERS CERTIFICATION
 This well was drilled under my supervision and the report is true to the best of my knowledge.
 Name Hi-Sierra Drilling Contractor
 Address Box 901 Minden, Nev. Contractor
 Nevada contractor's license number _____
 Nevada contractor's drillers number _____
 Nevada driller's license number 763 Actual Driller
 Signed Tony Kawchak Contractor
 Date 12-8-82

BAILER TEST
 G.P.M. 20 Draw down 15 feet 2 hours
 G.P.M. _____ Draw down _____ feet _____ hours
 G.P.M. _____ Draw down _____ feet _____ hours