WHITE—DIVISION OF WATER RESOURCES
CANARY—CLIENT'S COPY
PINK—WELL DRILLER'S COPY

STATE OF NEVADA
DIVISION OF WATER RESOURCES

WELL DRILLER'S REPORT

Please complete this form in its entirety

OFFICE USE ONLY
Log No. 3286
Permit No. 5340
Basin 8-05

PRINT OR TYPE ONLY

NOTICE OF INTENT NO. 13416

1. OWNER Ed Jones, Etal
MAILING ADDRESS Box 18 [illegible]
Fallon, NV 89406

ADDRESS AT WELL LOCATION Stillwater 5 [illegible]

2. LOCATION NW ¼ NW ¼ Sec. 30 T. 14 N/S R. 26 E. Douglas County
PERMIT NO. 4-105-4-3266 (Issued by Water Resources) | Parcel No. | None (Subdivision Name)

3. TYPE OF WORK
New Well ☐ Recondition ☑
Deepen ☐ Other ☐

4. PROPOSED USE Recreation
Domestic ☐ Irrigation ☐ Test ☐
Municipal ☑ Industrial ☐ Stock ☐

5. TYPE WELL
Cable ☐ Rotary ☑
Other ☐

6. LITHOLOGIC LOG

Material	Water Strata	From	To	Thickness
Drilled A 6" hole to 60'				
Installed PVC pipe to 60 feet.				
Pumped 5½ yds Neat Cement grout using tremie & bailer. Grout topped off at surface				
Pulled stop pump in well to stop bridge water in casing during grouting. Service Pump pump for 48 hours since grout was setting				
See Construction for other details				

Date started 1-5, 19 96
Date completed 1-8, 19 96

7. WELL TEST DATA

Pump RPM	G.P.M.	Draw Down	After Hours Pump

BAILER TEST
G.P.M. ..... Draw down ..... feet ..... hours
G.P.M. ..... Draw down ..... feet ..... hours
G.P.M. ..... Draw down ..... feet ..... hours

8. WELL CONSTRUCTION
Diameter ..... inches Total depth 230 feet
..... inches
..... inches
Casing record 8 5/8"
Weight per foot ..... Thickness .....

Diameter	From	To
8 5/8 inches	1 3 feet	23 2 feet
inches	feet	feet
inches	feet	feet
inches	feet	feet
inches	feet	feet
inches	feet	feet

Surface seal: Yes ☐ No ☐ Type .....
Depth of seal ..... feet
Gravel packed: Yes ☐ No ☐
Gravel packed from ..... feet to ..... feet

Perforations:
Type perforation Hole saw
Size perforation Unknown
From ..... feet to ..... feet
From ..... feet to ..... feet
From ..... feet to ..... feet
From ..... feet to ..... feet
From ..... feet to ..... feet

9. WATER LEVEL
Static water level Flowing feet below land surface
Flow 100+ G.P.M. ..... P.S.I.
Water temperature Unknown Quality .....

10. DRILLER'S CERTIFICATION
This well was drilled under my supervision and the report is true to the best of my knowledge.
Name A & A Pump Co (Contractor)
Address Carson City, Nevada (Contractor)
Nevada contractor's license number issued by the State Contractor's Board 23195
Nevada contractor's driller's number issued by the Division of Water Resources .....
Nevada driller's license number issued by the Division of Water Resources, the on-site driller 11420
Signed [signature] (By driller performing actual drilling on site or contractor)
Date 1-11-96

(Rev. 11-85) USE ADDITIONAL SHEETS IF NECESSARY (O)-627

LOG 32866

A & H PUMP CO.
5551 Hwy. 50 East #3
Carson City, Nevada 8970[illegible]
883-0459 - 883-40[illegible]
885-1889

Jan 15, 1990

TED BROWN, ET AL
P.O. BOX 18599
RENO, NEVADA 89511

CEMENTING around 8" well:

DRILLED FOUR 6" HOLES TO SIXTY FEET AND INSTALLED GROUT PIPE. HOOKED UP GROUT PLANT AND PUMPED FIVE AND ONE-HALF YARDS OF GROUT AROUND CASING. GROUT RETURNED TO THE SURFACE.

PRIOR TO GROUTING, WE INSTALLED A 5 HP 120 GPM PUMP IN WELL TO PULL WATER LEVEL DOWN BELOW SURFACE. DURING GROUTING, GROUT APPEARED IN WATER, BUT WATER CLEARED UP. THIS SIGNIFIES THAT THERE IS A BREAK IN THE CASING.

PUMP IN WELL WAS LEFT PUMPING FOR NINETY FOUR HOURS WHILE GROUT WAS SETTING UP AROUND CASING.

RAN CAMERA IN CASING AND CAMERA SHOWED AN ABNORMAL CONDITION IN CASING BETWEEN EIGHT & NINE FEET.

Quinton Butts