

OFFICE USE ONLY
 Log No. 37290
 Permit No. 91-
 Basin 91-

PRINT OR TYPE ONLY
 DO NOT WRITE ON BACK

WELL DRILLER'S REPORT

Please complete this form in its entirety in accordance with NRS 534.170 and NAC 534.340

NOTICE OF INTENT NO. 18243

1. OWNER Trandec, Inc ADDRESS AT WELL LOCATION River Park - Reno
 MAILING ADDRESS 600 W Broadway Suite 220
Glendale, Ca 91204

2. LOCATION NE 1/4 SW 1/4 Sec. 13 T 19 N/S R. 18 E Washoe County
 PERMIT NO. 38-530-28

Issued by Water Resources Parcel No. Subdivision Name

3. WORK PERFORMED
 New Well Replace Recondition
 Deepen Abandon Other

4. PROPOSED USE
 Domestic Irrigation Test
 Municipal/Industrial Monitor Stock

5. WELL TYPE
 Cable Rotary RVC
 Air Other

6. LITHOLOGIC LOG

| Material | Water Strata | From | To | Thick-ness |
|--|--------------|------|----|------------|
| 6 inch domestic well | | | | |
| This well was 103 ft T.D. | | | | |
| Aqua perforated from top to bottom & ran tremie tube to 97 ft to pump neat cement to surface | | | | |
| 5076 #'s neat cement | | | | |

8. WELL CONSTRUCTION

Depth Drilled _____ Feet Depth Cased _____ Feet

HOLE DIAMETER (BIT SIZE)

From _____ To _____

Inches _____ Feet _____ Feet

Inches _____ Feet _____ Feet

Inches _____ Feet _____ Feet

CASING SCHEDULE

| Size O.D. (Inches) | Weight/Ft. (Pounds) | Wall Thickness (Inches) | From (Feet) | To (Feet) |
|--------------------|---------------------|-------------------------|-------------|-----------|
| | | | | |
| | | | | |
| | | | | |
| | | | | |

Perforations:

Type perforation _____

Size perforation _____

From _____ feet to _____ feet

Surface Seal: Yes No Seal Type: Neat Cement Cement Grout Concrete Grout

Depth of Seal _____

Placement Method: Pumped Poured

Gravel Packed: Yes No

From _____ feet to _____ feet

Date started 8/29/91, 19____

Date completed 8/29/91, 19____

7. WELL TEST DATA

TEST METHOD: Bailer Pump Air Lift

| G.P.M. | Draw Down (Feet Below Static) | Time (Hours) |
|--------|-------------------------------|--------------|
| | | |
| | | |
| | | |
| | | |
| | | |

9. WATER LEVEL

Static water level 7 feet below land surface

Artesian flow _____ G.P.M. _____ P.S.I.

Water temperature _____ °F Quality _____

10. DRILLER'S CERTIFICATION

This well was drilled under my supervision and the report is true to the best of my knowledge.

Name Aqua Drilling & Well Service, Inc
 Contractor
 Address 625 Spice Islands Dr Suite L
Sparks, Nv 89431
 Contractor

Nevada contractor's license number 15291
 issued by the State Contractor's Board

Nevada driller's license number issued by the 1132
 Division of Water Resources, the on-site driller

Signed Roger M. Thrall
 By driller performing actual drilling on site or contractor

Date Roger M. Thrall 9/30/91

'91 OCT 18 AM 10:27 RECEIVED STATE ENGINEERS OFFICE