DIVISION OF WATER RESOURCES

STATE OF NEVADA
DIVISION OF WATER RESOURCES

WELL DRILLERS REPORT

Please complete this form in its entirety

OFFICE USE ONLY
Log No. 58402
Permit No.
Basin 212

Deepening Job-

MESA VERDE LN.

1. OWNER Charleen Anthony ADDRESS 107 ~~Meda~~ Verde Ln.

2. LOCATION SE ¼ SW ¼ Sec. 9 T. 22 N/S R. 61 E Clark County
PERMIT NO.

3. TYPE OF WORK
New Well ☐ Recondition ☐
Deepen ☒ Other ☐

4. PROPOSED USE
Domestic ☒ Irrigation ☐ Test ☐
Municipal ☐ Industrial ☐ Stock ☐

5. TYPE WELL
Cable ☒ Rotary ☐
Other ☐

6. LITHOLOGIC LOG

Material	Water Strata	From	To	Thickness
Black grey slime		176	180	4
Dark red caly		180	196	16
Gravel seal broke here				
~~XXXXXXXXXXXXXXXX~~				
Clay, Water & pea gravel	X	196	280	84

RECEIVED
DEC 1 ? 1974
Div. of Water Resources
Branch Office — Las Vegas, Nev.

Date started July 1974, 19
Date completed July 1974, 19

7. WELL TEST DATA

Pump RPM	G.P.M.	Draw Down	After Hours Pump

BAILER TEST
G.P.M. 40 Draw down 30 feet ½ hours
G.P.M. Draw down feet hours
G.P.M. Draw down feet hours

8. WELL CONSTRUCTION
Diameter hole 7 inches Total depth 280 feet
Casing record
Weight per foot 10.6 Thickness 10gage

Diameter	From	To
6 inches	170 feet	280 feet
inches	feet	feet
inches	feet	feet
inches	feet	feet
inches	feet	feet
inches	feet	feet

Surface seal: Yes ☐ No ☐ Type
Depth of seal feet
Gravel packed: Yes ☐ No ☒ was - dark out
Gravel packed from feet to feet

Perforations:
Type perforation Torch
Size perforation 1/8 " X 12"
From 170 feet to 280 feet
From feet to feet
From feet to feet
From feet to feet
From feet to feet

9. WATER LEVEL
Static water level 92 Feet below land surface
Flow G.P.M.
Water temperature ° F. Quality

10. DRILLERS CERTIFICATION
This well was drilled under my supervision and the report is true to the best of my knowledge.

Name Douglas Slagle
Address 4518 E. Vegas Valley Dr.
Nevada contractor's license number 3325
Nevada driller's license number 137
Signed Douglas Slagle
Date

USE ADDITIONAL SHEETS IF NECESSARY

5471