

PRINT OR TYPE ONLY
DO NOT WRITE ON BACK

WELL DRILLER'S REPORT

Please complete this form in its entirety in accordance with NRS 534.170 and NAC 534.340

NOTICE OF INTENT NO. 32544

Consultant: CDM Engineers & Constructors Inc. Client: Santa Fe Pipeline
 1. OWNER: 50 W. Liberty, Suite 770 ADDRESS AT WELL LOCATION: Vista Canyon Group Sparks Solvent/Fuel Site
 MAILING ADDRESS: Reno, Nevada 89501 Sparks, Nevada
 2. LOCATION: NW 1/4 NE 1/4 Sec. 9 T. 19N N/S R. 20 E. Washoe County
 PERMIT NO. M/O 913 E-1 34-101-25 Sparks Solvent/Fuel Site
Issued by Water Resources Parcel No. Subdivision Name

3. WORK PERFORMED: New Well Replace Recondition
 Deepen Abandon Other _____
 4. PROPOSED USE: Domestic Irrigation Test
 Municipal/Industrial Monitor Stock
 5. WELL TYPE: Cable Rotary RVC
 Air Other: TUBEX

6. LITHOLOGIC LOG

| Material | Water Strata | From | To | Thickness |
|--|--------------|------|------|-----------|
| Lt. gray brown subangular to subround sand w/ angular to subround gravel, abundant cobbles and minor silt, med. dense, moist | | 0 | 30 | 30 |
| Color changed to lt. brown below 29ft. | | | | |
| Color change to lt. red brown, saturated below 30ft. | | | | |
| Lt. red brown sand w/ gravel abundant cobbles and minor silt, med. dense, moist | | 30 | 63.7 | 33.7 |

8. WELL CONSTRUCTION
 Depth Drilled 63.7 Feet Depth Cased 63 Feet
 HOLE DIAMETER (BIT SIZE)
 From To
11 1/2 Inches 0 Feet 63.7 Feet
 _____ Inches _____ Feet _____ Feet
 _____ Inches _____ Feet _____ Feet

CASING SCHEDULE

| Size O.D. (Inches) | Weight/Ft. (Pounds) | Wall Thickness (Inches) | From (Feet) | To (Feet) |
|--------------------|---------------------|-------------------------|-------------|-----------|
| 6" | w/cap | SCH 80 PVC | 0 | 17.1 |
| 6" | | SS Sump w/cap | 57.6 | 63 |
| Centralizers | | 57,36,16 SS | | |

Perforations:
 Type perforation Factory sawed Slot
 Size perforation .100 slot SS wire wrapped
 From 17.1 feet to 57.6 feet
 From _____ feet to _____ feet
 Surface Seal: Yes No Seal Type:
 Depth of Seal 3 - 12.1 Neat Cement
 Placement Method: Pumped Cement Grout
 Bentonite Seal: Poured 12.1 - 14.1 Concrete Grout
 Gravel Packed: Yes No 1/4-1/8" well sand
 Filter 14.1 - 15.1 #20 feet to 15.1 - 63.7 feet

9. WATER LEVEL
 Static water level not known feet below land surface
 Artesian flow _____ G.P.M. N/A P.S.I.
 Water temperature N/A °F Quality N/A

Date started 5-1-95, 19_____
 Date completed 5-2-95, 19_____

7. WELL TEST DATA

TEST METHOD: Bailer Pump Air Lift

| G.P.M. | Draw Down (Feet Below Static) | Time (Hours) |
|---------|-------------------------------|--------------|
| No test | | |

10. DRILLER'S CERTIFICATION
 This well was drilled under my supervision and the report is true to the best of my knowledge.
 Name WAYNE DRILLING, INC. Contractor
 Address P.O. BOX 12370 Contractor
RENO, NEVADA 89510
 Nevada contractor's license number 22549
 issued by the State Contractor's Board.
 Nevada driller's license number issued by the Division of Water Resources, the on-site driller 908
 Signed [Signature]
 By driller performing actual drilling on site or contractor
 Date February 5, 1996