

Log No. 64898
 Permit No. _____
 Basin. 099

PRINT OR TYPE ONLY
 DO NOT WRITE ON BACK

WELL DRILLER'S REPORT

Please complete this form in its entirety in accordance with NRS 534.170 and NAC 534.340

NOTICE OF INTENT NO. 31061
30 SHELTON
RANCHO HAVEN, NV.

1. OWNER ROBT LEXA ADDRESS AT WELL LOCATION 30 SHELTON
 MAILING ADDRESS 5302 VISTA RIDGE WY. RANCHO HAVEN, NV.
RENO, NV 89523
 2. LOCATION SE 1/4 SW 1/4 Sec. 9 T. 23 N N/S R. 18 E WASHOE County
 PERMIT NO. 5597 Issued by Water Resources Parcel No. 78-161-11 Subdivision Name RANCHO HAVEN

3. WORK PERFORMED
 New Well Replace Recondition
 Deepen Abandon Other _____
 4. PROPOSED USE
 Domestic Irrigation Test
 Municipal/Industrial Monitor Stock
 5. WELL TYPE
 Cable Rotary RVC
 Air Other _____

6. LITHOLOGIC LOG

Material	Water Strata	From	To	Thick-ness
HOLE HAD CASING REMOVED AND HAD COLLAPSED TO 6' DEPTH.				
NO WATER EVIDENT IN UPPER PORTION OF BOREHOLE				
POURED CONCRETE GROUT MATERIAL UNTIL CONCRETE WAS WITHIN 8' OF SURFACE BECAUSE PROPERTY OWNER WAS GOING TO LOWER GRADE LEVEL APPROX 8'				
THIS PROCESS WAS OK'D WITH WASHOE COUNTY DIV. OF ENVIRONMENTAL HEALTH INSPECTOR BROWN PRIOR TO DOING WORK				

8. WELL CONSTRUCTION
 Depth Drilled _____ Feet Depth Cased _____ Feet
 HOLE DIAMETER (BIT SIZE)
 From 10 Inches To ±64 Feet
 _____ Inches _____ Feet
 _____ Inches _____ Feet
 _____ Inches _____ Feet
 CASING SCHEDULE

Size O.D. (Inches)	Weight/Ft. (Pounds)	Wall Thickness (Inches)	From (Feet)	To (Feet)
NONE - 6 5/8 REMOVED				

 Perforations:
 Type perforation _____
 Size perforation _____
 From _____ feet to _____ feet
 Surface Seal: Yes No Seal Type:
 Depth of Seal 64' Neat Cement
 Cement Grout
 Placement Method: Pumped Concrete Grout
 Poured
 Gravel Packed: Yes No
 From _____ feet to _____ feet

Date started 4-9 1966
 Date completed 4-9 1966

7. WELL TEST DATA

TEST METHOD:	G.P.M.	Draw Down (Feet Below Static)	Time (Hours)
<input type="checkbox"/> Bailer <input type="checkbox"/> Pump <input type="checkbox"/> Air Lift			

9. WATER LEVEL
 Static water level _____ feet below land surface
 Artesian flow _____ G.P.M. _____ P.S.I.
 Water temperature _____ °F Quality _____

10. DRILLER'S CERTIFICATION
 This well was drilled under my supervision and the report is true to the best of my knowledge.
 Name DELAP DRILLING Co. Contractor
 Address PO BOX 178 Contractor
WEST POINT, CA 95255
 Nevada contractor's license number 39825
 issued by the State Contractor's Board.
 Nevada driller's license number issued by the 1476
 Division of Water Resources, the on-site driller.
 Signed _____ By driller performing actual drilling on site or contractor
 Date _____