STATE OF NEVADA
DIVISION OF WATER RESOURCES
WELL DRILLER'S PLUGGING REPORT

OFFICE USE ONLY
Log No.
Permit No.
Basin

PRINT OR TYPE ONLY
DO NOT WRITE ON BACK

Please complete this form in its entirety in accordance with NRS 534.170 and NAC 534.340

NOTICE OF INTENT NO. 74825
WELL NAME *(If applicable)*: BW-43

1 OWNER Barrick Goldstrike Mines Page (2 of 3)
MAILING ADDRESS PO Box 39, Elko, NV 89803

ADDRESS AT WELL LOCATION Barrick Goldstrike Mine Site
25 miles North of Carlin, NV
Subdivision Name: N/A *County:* Elko

2 LOCATION SW ¼ SE ¼ Sec 13 T 36N N/S R 49 E
PERMIT/WAIVER No. 69695 *Issued by Water Resources* R-928 *Parcel No.*

Latitude 40° 59.494N
Longitude 116° 28.086W
UTM E
N
☐ NAD 27
■ NAD 83/WGS 8

3 TYPE OF WELL
☐ Domestic ■ Municipal/Industrial ☐ Irrigation ☐ Monitor ☐ Test ☐ Stock

Is this well being plugged because a replacement well was drilled? No
If yes, what is replacement well NO?

Is there an existing well log? Yes
If yes, what is NDWR well log #? 100930

4 *EXISTING WELL CONSTRUCTION*
Depth Drilled 2800 Feet Depth Cased 2800 Feet

EXISTING CASING SCHEDULE

Size O.D. (Inches)	Weight/Ft. (Pounds)	Wall Thickness (Inches)	From (Feet)	To (Feet)
24	94.62	0.375	580.90	620.98
24	110.09	0.4375	620.98	861.52
24	94.62	0.375	861.52	901.66
24	110.09	0.4375	901.66	1062.06

Existing Perforations:
Type of perforation Louvered
Size of perforation 0.125"
From 2191.44 2800 feet
From feet
From feet
From feet
From feet

5 *WATER LEVEL*
Static water level feet below land surface
Artesian flow G.P.M. P.S.I
Water temperature °F Quality

6 Additional Notes or Comments

7 WELL PLUGGING PROCEDURE
Was well cleaned out to total depth? ■ yes ☐ no
If well was not cleaned out to total depth, please explain why:
Ran BQ tremie pipe from surface to 2800 feet. Well was clean.

Was the well contaminated? ☐ yes ■ no
Was the casing pulled? ☐ yes ■ no If pulled from: feet to feet
Was the casing over drilled? ☐ yes ■ no
If casing was left in place, please show where additional perforations were made:
Additional Perforations:
Type of perforator used:
From feet to feet Number of perfs per linear foot
From feet to feet Number of perfs per linear foot
From feet to feet Number of perfs per linear foot
From feet to feet Number of perfs per linear foot
From feet to feet Number of perfs per linear foot
From feet to feet Number of perfs per linear foot
From feet to feet Number of perfs per linear foot
From feet to feet Number of perfs per linear foot
From feet to feet Number of perfs per linear foot
From feet to feet Number of perfs per linear foot
From feet to feet Number of perfs per linear foot
From feet to feet Number of perfs per linear foot

8 WELL PLUGGING MATERIALS
Material Used
From feet to feet ☐ Pumped ☐ Poured
From feet to feet ☐ Pumped ☐ Poured
From feet to feet ☐ Pumped ☐ Poured
From feet to feet ☐ Pumped ☐ Poured
From feet to feet ☐ Pumped ☐ Poured
From feet to feet ☐ Pumped ☐ Poured
Neat Cement Fluid Weight lbs/gal
Bentonite Grout % bentonite
Date Started 7-Aug-16
Date Completed 11-Aug-16

9 DRILLER'S CERTIFICATION
This well was plugged and abandoned under my supervision and the report is true to the best of my knowledge.
Name Boart Longyear Company *Contractor*
Address 2745 W California Ave, Salt Lake City, Utah 84104 *Contractor*
Phone (801) 973-6667
Nevada contractor's license number issued by the *State Contractor's Board* 0021976
Nevada driller's license number issued by the Division of Water Resources, the *on-site driller* 1995
Signed *By driller performing actual drilling on site or contractor*
Date 8-17-16

(Rev 04 16)

USE ADDITIONAL SHEETS IF NECESSARY