

**WELL DRILLER'S REPORT**

**PRINT OR TYPE ONLY**  
**DO NOT WRITE ON BACK**

Please complete this form in its entirety in accordance with NRS 534.170 and NAC 534.340

OFFICE USE ONLY  
Log No. **80761**  
Permit No. **215**  
Basin. **215**

NOTICE OF INTENT NO. **24459**

1. OWNER Seam Group Resorts ADDRESS AT WELL LOCATION Seam Group

MAILING ADDRESS Seam Group Resorts ADDRESS AT WELL LOCATION Seam Group

2. LOCATION 1/4 Sec 14, 32, 1/4 Sec 6 T 19 N R 03 E County Clark

PERMIT NO. 10-310-011 Parcel No. Seam Group Subdivision Name Resorts

3. WORK PERFORMED  New Well  Replace  Recondition  Abandon  Other

PROPOSED USE  Domestic  Municipal/Industrial  Irrigation  Monitor  Stock  Test  Cable  Rotary  RVC  Air  Other

6. LITHOLOGIC LOG

Material	Water Strata	From	To	Thick-ness
Gravel		0	3	
Sand		3	45	
Gravel		45	50	

8. WELL CONSTRUCTION

Depth Drilled 50 Feet 50 Feet

HOLE DIAMETER (BIT SIZE)

Inches	From	To
11	0	52

CASING SCHEDULE

Size O.D. (Inches)	Weight/Ft. (Pounds)	Wall Thickness (Inches)	From (Feet)	To (Feet)
4		3/16	0	Surface

Perforations: Type perforation 220 PVC

Size perforation 220 feet to 20 feet

From 20 feet to 20 feet

Surface Seal:  Yes  No Seal Type:  Neat Cement  Cement Grout  Concrete Grout

Depth of Seal 16'

Placement Method:  Pumped  Poured

Gravel Packed:  Yes  No 18' feet

9. WATER LEVEL

Static water level 22 feet below land surface

Artesian flow 22 G.P.M. P.S.I.

Water temperature 72 °F Quality Good

10. DRILLER'S CERTIFICATION

This well was drilled under my supervision and the report is true to the best of my knowledge.

Name DAVE DANNE Contractor

Address 2420 S. VANDERBILT Contractor

7. WELL TEST DATA

TEST METHOD:  Bailor  Pump  Air Lift

Date started 8/7/00 1900

Date completed 8/7/00 1900

G.P.M. 2420 Draw Down (Feet Below Static) 22

Time (Hours) 11:14